NOV 2 1 1997

For corners in

4. Lot No.

LIBER

2 PAGE 148

COMMISSION

_ , Recorded Plat

REMOUNUMENTION

RECEIVED FOR RECORD

97 SEP -9 AM 8: 58

LIBER NO PAGE NO 148

REGISTER OF DEEDS
SANILAC CO. MICHIGAN

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

| Sanilac (County) | Located In: | Corner Code # | |
|--|----------------------------------|---------------|--|
| 1. Public Land Survey | T10NR 13E TR TR | <u>K - 1</u> | |
| Property Controlling in Section Miscellaneous Property in Sec. | S T R S T R S T R S T R | teg.2 | |

Register of Deeds Stamp & File Number

5. Private Claims

John A Milletics , in a field survey on June 21 , 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the conformance with regulations and rules therefore as required in the current manual or survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,

NOTE: Not more than 2 corners, all in the same town and range, may be recorded

| 1 A B C D | E F | G H | ΙJ | KLM |
|------------|----------|------|-----------------|--------------|
| 2 - 6 - 5 | | | 1 1 | |
| 3 | <u> </u> | 1-1- | 7-2- | |
| 4 - 7 - 8- | | | | 1-1-1 |
| 5 | | 10- | —-11— | 12 |
| 6 18 17 | 16 | | | 1-1- |
| 7 | | 15- | 14_ | 13 |
| 8 19 20 | 21_ | | | |
| 9 | | 22- | —23.— I | 24 |
| 10 30 29 | -28- | | _ | |
| 11 | | -27 | -26- | -25- |
| 12 31 32 | 32 | 34 | 1 | |
| 13 |) | -34- | -3 ⁵ | -36- |
| | | | | |

A. Description of original monument and accessories and/or subsequent restoration;

GLO Notes Birch 12, S79E 45½ Birch 10 S09W

APPROVED PEER BOARD MEETING 18,1987 M

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Monu Box - removed by Sanilac County Road Comm. during reconstruction of road, REPLACED using Act 74 recording Liber 1 Page 425

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

NW Corner Section 1 T10N-R13E Moun Box with iron & cap

East 75.15 to the SE Corner Section 34 (MONU BOX)

N60°E 135.30 to a nail in a Tele Pole

S30°E 38.20 to a Stop Sign

N45°E 68.42 to a Stop Sign

NO5°W 19.56 to West leg of a Road Sign

NO5°E 19.59 to East leg of a Road Sign

East 2652.48 to the N 1/4 Corner Section 1

JAHI) Signed by

Surveyor's Michigan License No. 25859

Think of Metalling John A. Milletics Land Surveyor No. 25859 Manual Sur

Date_ Aug 11, 1997