NOV 2 1 1897

LIBER

2 PAGE 145

COMMISSION

REMOUNUMENTION

RECEIVED FOR RECORD

	- 97	SLY - 9	AM	Q:	20
		-			K/C
•	1050	un col	AGE	ΝO.	170
L,	IDEN	ND STHE	RIF	F	
			1 1 1 1		_

REGISTER OF DEEDS SANILAC CO. MICHIGAN

	LAND CORNER RECORDATION CERTIFICATION
or corners in	Filing Requirement of Act 74, Mich. P.A. 1970

Sanilac Located in: Corner Code # 1. Public Land Survey T10NR 13E H - 12. Property Controlling in Section 3. Miscellaneous Property in Sec.

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat 5. Private Claims

John A Milletics, in a field survey on June 21, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.

1	<u>A</u>	В	С	D	E	F	G	H	I	J	ĸ	L	١
2		6-	_	- 5-		- 4		Ţ_		1		Ţ	_
3	L	1_	-	Ĭ.,	_	Ţ	_	Ĭ	\perp	1			_
4	_	ļ 7.—	_	- 8 	_	ا ــو .	4	-10	\perp	11-	_	 -12	
5	-	-		-	\downarrow	\perp	\bot	_ _	ļ	<u> </u>	_	Ţ.	
6	<u> </u> :	i 1 <mark>,8</mark> —	-	17—	╄-	 16_	1	 -15		 14—	_	 13—	
7	<u> </u>	<u> </u>	1	1	_	_	_			ot			
8	1	9	<u> </u>	 20	<u> </u>	 21—	$oldsymbol{\perp}$	-22_	L,	 23	L,	Ţ 24—]
9		_	_	<u> </u>	ļ	\perp	$oldsymbol{\downarrow}$		_	L			Į
10	;] 	-	ا 29—	 	 28	_	27	<u> </u>	 26—	1_2	 ?5	
11		-	-	-		-	+	_	<u> </u>	ļ	ļ	<u> </u>	1
12	3	1	 -3	32	<u> </u>	33—	┼	34	<u> </u>	[5	 _:	! 36—	ļ
		ſ	ı	ı	ŀ	ı	1	1	1	ĺ	į.	I	ı

A. Description of original monument and accessories and/or subsequent restoration:

H - 1

NO GLO Notes Avalible

APPROVED PEER BOARD MEETING 18, 1997 97

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Monu Box - removed by Sanilac Co. Road Comm. during reconstruction of Road, REPLACED using Act 74 recording Liber 1 Page 423

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H - 1

N 1/4 Cor Section 3 T10N-R13E

Monu Box Set with iron & cap

East 34.48 to the S 1/4 Corner Section 33 (Monu Box)

East 2639.06 to the SE Cor Section 3

West 2639.06 to the SW Cor Section 3

N40°E 38.00 to the North End of a 36" CMP

S40°E 39.00 to the South End of a 36" CMP

Signed by_ Surveyor's Michigan License No._ 25859

Date ___ Aug 11, 1997

