REMONUMENTATIO

LIBER

2 PAGE 122

RECEIVED FOR RECORD

NOV 2 1 1997

COMMISSION

REMOUNUMENTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

97 SEP -9 AM 8: 56

LIBER NO PAGE NO. 126
REGISTER OF DEEDS
SANIL AC CO. MICHIGAN

Car	^^	m	And	· ir

Sanilac	Located In:	Corner Code #	i
(County)			
1. Public Land Survey	T <u>10N</u> R TR TR TR	14E A - 1	
Property Controlling in Section Miscellaneous Property in Sec.	S TR S TR S TR		Registe

Register of Deeds Stamp & File Number

. Lot No,	Recorded Plat	
Private Claims		

I, John A Milletics, in a field survey on June 21, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A 1	B (C E)]	Ε	F	G	H	I	J	K	L	M
1 4	1	Γ						ŀ		T			
2	-	6	 -	5 -	_	4	┿	ڋ	╁	- 2 -	+	- <u>İ</u> .	
3	L_				<u> </u>	_	-	-	\bot	_	_	-	
4	<u> </u>	 7		 8	L	 9	 	10-	+	-11-	+	 -12	
5	<u> </u>						╀┈			+	+	+	
6	1	l . 8	1	7	<u>_</u> ,	l 6	<u> </u>	 15		 -14-	_	 -13	
7		Ĺ		Ĺ				Ĩ	<u>.l</u>			Ĺ	
·			Ι.]	1				
8	I	.9— !	-2	0—		21— 	十	.22 <u>—</u> I	T	-23 1		-24	
9	<u> </u>	<u> </u>	 				╁	╁	- -		+	+	
10	-	ļ 0	 2	9		! 28—	+	.27 I	+	-26-	+	-25 I	
11	_		-		ļ	-	╁	╁	+-	+	+	+	
12	3	! 1	 _3	2 I	<u> </u> -:	3 3—	+	.3 <mark>4</mark> —	+-	-35– -35–	+	-36	
13	L				ĹĹ	<u> </u>		Л.		<u>.</u>			

A. Description of original monument and accessories and/or subsequent restoration:

A - 1

GLO Notes

Hemlock 9 S22W 12

Hemlock 9 S57E 21

APPROVED PEER BOARD MEETING

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A - 1

Found Monu Box - removed by Sanilac County Road Comm, during reconstruction of Road, REPLACED using Act 74 recorded in Liber 1 Page 426

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A - 1

NW Corner Section 6 T10N-R14E

Monu Box with iron and cap

East 106.68 to the SE Corner Section 35 (MONU BOX)

S45°E 100.50 to a nail in a Power Pole

 $N40^{\circ}E$ 78.93 to a riser box

 $N60^{\circ}E$ 99.06 to a stop sign

Surveyor's Michigan License No._

N45°E 80.00 to a nail in a Power Pole

East 972.06 to the N 1/4 Cor Section 6

Signed by ANTIALLO

Aug 11, 1997

Date

John A. Milletics Land Surveyor No. 25859

REVISED OCT., 1995