Ri For	EMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 Sanilac EMONUMENT 1995 Located In: Corner Code ##	94 DEC 16 AM 9: 40 LIBER NO. 1 PAGE NO. 181
	Corners in Sulling Requirement of Act 74, Mich. P.A. 1970 Sanilac MONUMENT 1995 Located In: Corner Code ## Public Land Survey T 10N R 14E K - 13 T R T R T R	ESTHER LEE REGISTER OF DEEDS SANILAC CO., MICHIGAN
1.	Public Land Survey T 10N R 14E K - 13 T R T R	
	T R	ister of Deeds Stamp & File Number
4.	Property in Sec. S T R	
1, _do in 1 cur Ma abo	Private Claims John A Milletics, in a field survey on Dec 5, 19 94 hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned ines 1 and 2 above were in conformance with regulations and rules therefore as required in the rent manual of survey instructions of the United States Department of the Interior, Bureau of Land nagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 over were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a court of Law; established, re-established, monumented, re-monumented, recovered, found as pressed below:	A B C D E F G H J K L N 2
NC	TE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.	11 12 31 32 33 34 35 36
A.	Description of original monument and accessories and/or subsequent restoration: K - 13 GLO Notes Set Post Corner: Birch 11 N 28 W 25, Birch 18 N 73½ E 32 Act 74 Form NONE Act 132 Form Liber 4 Page 133 Unrecorded Surveys Dated 12-23-92	N
	Road Comm NONE Drain Comm NONE	
В.	Description of corner evidence found and/or method applied in restoring or reestablishing K - 13 SE Cor Section 35 T10N-R14E Found 1/2" Iron Bar West 1.98 to a 1/2" Iron Bar in the Road Bed N45°W 59.08 to a nail in a Power Pole N40°W 34.73 to a Stop Sign N45°E 133.1 to a nail ina Power Pole S30°E 34.25 to a stop sign post	Approved Peer Board Meeting Dec 16, 1994
C.	Description of monument for corner and accessories established to perpetuate locating the K - 13 SE Cor Section 35 T10N-R14E Found 1/2" Iron Bar West 1.98 to a 1/2" Iron Bar in the Road Bed N45°W 59.08 to a nail in a Power Pole N40°W 34.73 to a Stop Sign N45°E 133.1 to a nail in a Power Pole S30°E 34.25 to a stop sign post	John A. Milletics Land Surveyor No. 25859
_	ned by	1994
Surveyor's Michigan License No. 25859		

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28. 1971 REVISED MAY 14. 1975 REVISED JAN., 1983