r 4	,
the the the time of the same	١,
THE WAR THE WAR A STATE OF THE PARTY OF THE	
HEMONUMENTATION	

LIBER

2 PAGE 127

RECEIVED FOR RECORD

the same of the sa

NOV 2 1 1997

REMOUNUMENTION

97 SEP -9. AM 8: 57

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

LIBER NO 2 PAGE HO 127
REGISTER OF DEEDS

For corners in	<u>-</u>	REGISTÉR OF DEEDS SANILAC COLMICHIGAN
Sanilac (County)	Located In: Corner Code #	
1. Public Land Survey	T10N R14E T R F-1 T R J	
Property Controlling in Section Miscellaneous Property in Sec.	S TR S TR S TR S TR	Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat ______
5. Private Claims _____

I, <u>John A Milletics</u>, in a field survey on <u>June 21</u>, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management of ya decree of a Court of Law and for United States Department of the Interior, Bureau of Land Management of with the rules of the Michigan that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.

а в с	D E	F G	н 1	JK	L M
1		4	_3_	_2_	
2 6 3					
4 - 7-	- 8-	9	10	-11	12-
5					
6 18	17-	16	15	1'4	-13-
7	 		-	23	24-
819	2'O	21	22	23	
9	1-1-	28	27-	26-	25
10 30	29-				
11 12 -31-	32_	33_	34	35	-36-
12				<u> </u>	

A. Description of original monument and accessories and/or subsequent restoration:

GLO Note

No GLO Notes avalible

APPROVED PEER BOARD MEETING
Aug 18, 1997 9m

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: F = 1

Found Monu Box - removed by Sanilac County Road Comm, during reconstruction of Road, Replaced using Act 74 recorded Liber 1 Page 443

C.	Description of monument for corner and accessories established to perpetuate loc	eating the position of the corner:	Mighing
٠.	r 1	Will Stiffeet	100
	N 1/4 Cor Section 4 T10N-R14E		
	TOTAL TOTAL	John A.	Milletics 2
	The second of foot to a nail in a 20 hapto		urveyor 🔭 🚎
	gener int of feet to a nall in a consi	■ No. 2	3009
	and the control of th		4 0 2
	arger 101 62 feet to a nall lil d 20 100 per	11/0	Second Sille
	GIOOF O? 5? to a nall in a rence root	////ona	Saller
	GROUP OF 27 to a nail in a Mallova	· · · · · · · · · · · · · · · · · · ·	IIIIII.
	to the NW COY SECLION 4		
	Talkaron out to the NE Con December .	DateAug 15. 97	
S	igned by	-	
_	urvevor's Michigan License No. 25859		