## UNER 1 PAGE 402

## RECEIVED FOR RECORD

## REMONUMENTATION CORNER

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	DEC	-		•		
LiBER	RQ		FAG	EH(	少	<u>02</u>

Sanilac   Located In:   Corner Code ##   SANIL	STER OF DEEDS AC CO., MICHIGAN
T R	
· TR	
2. Property Controlling S T R	
3. Miscellaneous S T R R Register of Deeds S Property in Sec. S T R	Stamp & File Numb
4. Lot No, Recorded Plat A B C D	E F G H I J I
5. Private Claims	
2 - 6 - 5 - 3 3 - 1 - 1	<del>                                     </del>
4 7 1	
I, John A Milletics, in a field survey on Nov 3,	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned	16 15 14
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land	
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5	21 22 23
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  Court of Law; established, re-established, monumented, re-monumented, recovered, found as	
expressed below:	28 27 26
NOTE: Not more than 4 corners, all in the same town and range, may be recorded	<del>                                      </del>
on this certificate.	33 34 35
A. Description of original monument and accessories and/or subsequent restoration:	
E - 1 Found Monu Box, per survey recorded in Liber 4, Page 7	
of the Sanilac County Records.	
D - 1 Found 1/2" iron in blacktop, per survey dated Jan. 1987	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:	
E - 1 $D - 1$	
NE Cor Section 5 T10N-R15E N 1/4 Cor Section 5 T10N-R15E Found Monu Box Found 1/2" iron in blacktop	
SURV	EY &
REMONUM	
	1993
COMM	ISSION
C. Description of monument for corner and accessories established to perpetuate locating the position of the	corner:
E - 1 D - 1	
NE Cor Section 5 T10N-R15E  N 1/4 Cor Section 5 T10N-R15	E
Found Monu Box  Found 1/2" iron  North 17.70' to the East leg of a Road sign N05°E 29.35' to a nail in a	0011 22 -
North 17.70' to the East leg of a Road sign N05°E 29.35' to a nail in a S30°E 102.09' to a nail in a Power Pole N70°W 61.00' to a nail in a S40°W 121.07' to the NE Cor of a house South 61.70' to a nail in a S50°W 116.85' to a nail in a 30"ash	30" Maple

Signed by John A Millitre Date	Dec 15, 1993
Surveyor's Michigan License No. 25859	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19