

94 AUG 12 PM 2:38

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER NO. 1 PAGE NO. 468
ESTHER LEE
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

For corners in

Sanilac (County) Located In: Corner Code #

1. Public Land Survey T 10N R 15E M - 12, M - 13
T R
T R
T R
T R

2. Property Controlling S T R
in Section S T R

3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Register of Deeds Stamp & File Number

John A Milletics in a field survey on July 13, 19 94
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
M - 12 Found 1/2" Iron Bar in Gravel Road Bed, per survey dated 5-14-1980 Sanilac Land Surveying

M - 13 Found 1/2" iron bar in gravel road bed, per Choape survey recorded in Liber 3 on Page 5 of the Sanilac County Records.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	16	17	18	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

Approved Peer Board Meeting
Aug. 9, 1994

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M - 12
E 1/4 Cor Section 36 T10N-R15E
Found 1/2" Iron Bar

M - 13
SE Cor Section 36 T10N-R15E
Found 1/2" Iron Bar

SURVEY &
REMONUMENTATION

SEP 07 1994

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M - 12
E 1/4 Cor Section 36 T10N-R15E
1/2" Iron Bar
N85°W 47.30 to a nail S side of a Fence Post
West 50.00 to a 1/2" Iron Bar
S30°W 64.50 to the N End of a 36" CMP
S25°W 93.30 to the S End of a 36" CMP

M - 13
SE Cor Section 36 T10N-R15E
1/2" Iron Bar
N40°E 55.40 to a nail NW side of a Power Pole
S50°W 50.30 to a stop sign
N70°E 47.90 to a stop sign
S30°W 62.50 NE cor of a Michigan Bell Box

Signed by John A Milletics
Surveyor's Michigan License No. 25859

Date July 23, 1994