

REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE

93 DEC 15 PM 3:18

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 1 PAGE NO. 399  
ESTHER LEE  
REGISTER OF DEEDS  
SANILAC CO., MICHIGAN

For corners in

Sanilac (County) Located In: Corner Code #

1. Public Land Survey T 10N R 16E E - 1 F - 1

2. Property Controlling in Section S \_\_\_ T \_\_\_ R \_\_\_

3. Miscellaneous Property in Sec. S \_\_\_ T \_\_\_ R \_\_\_

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, John A Milletics, in a field survey on Nov 5, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

E - 1 Found 1/2" iron in gravel road bed, per survey recorded in Liber 4, Page 58 of the Sanilac County Records

F - 1 Found 1/2" iron in gravel road bed, per survey recorded in Liber 4, Page 64 of the Sanilac County Records

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E - 1  
NW Cor Section 4 T10N-R16E  
Found 1/2" iron bar

F - 1  
N 1/4 Cor Section 4 T10N-R16E  
Found 1/2" iron bar

SURVEY &  
REMONUMENTATION

1993

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E - 1  
NW Cor Section 4 T10N-R16E  
Found 1/2" iron bar  
North 19.09' to the West leg of a Road Sign  
S45°W 84.20' to a nail in a Power Pole  
S55°W 49.00' to a nail in a 18" Maple  
S30°E 41.65' to a Stop Sign

F - 1  
N 1/4 Cor Section 4 T10N-R16E  
Found 1/2" iron bar  
North 15.50' to the West leg of a Road Sign  
S50°E 61.10' to a nail in a Power Pole  
S40°E 55.35' to a nail in a Fence Post

Signed by John A Milletics Date Dec. 15, 1993

Surveyor's Michigan License No. 25859