NOV 2 1 1997

LIBER

2 PAGE 130

RECEIVED FOR RECORD

COMMISSION

REMOUNUMENTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

97 SEP - 9 AM 8: 57 LIBER NO. 21 PAGE NO. 130

REGISTER OF DEEDS SANILAC CO. MICHIGAN

For corners in

Sanilac	Located In:	Corner Code #		
(County)				
1. Public Land Survey	T_11NR12E TR	B - 13		
Property Controlling in Section Miscellaneous Property in Sec.	TR S TR S TR S TR	Seg-2		

Register of Deeds Stamp & File Number

4. Lot No	, Recorded Plat
Private Claims	

John A Milletics, in a field survey on May 21, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

а в с	D E	F G	н 1	J K	L M
1	$\neg \Box$			7 1	_ [
2 - 6-	- ∮	à -	- 3 	-2	— 1 — 1
3				┈┼─┼	-
4 - 7-		_ <u>}</u>	-10-	-11	12
5					
6 -18-	_1,7	_16	-15-	-14-	—-1 ^{'3} —
7	_+-+		_		
819	_20_	_21_	22	23	2'4
9					
10-30-	29	28	27	26-	25-
11-					
1 1	32-	33	34	35	36
12 31			1	}	
13				·	

A. Description of original monument and accessories and/or subsequent restoration;

B - 13

GLO NOTES

Hemlock 24 NO6°E 20

Hemlock 24 N75°W 34

APPROVED PEER BOARD MEETING Aug 18, 1997 gm

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B - 13

S 1/4 Corner Section 31 T11N-R12E

Found Monu Box in place - removed by Sanilac County Road Comm. during reconstruction of Road - REPLACED using Act 74 recorded in Liber 1 on Page 391

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B - 13

S 1/4 Corner Section 31 Tl1N-R12E

Monu Box with iron and cap

N10°E 75.18 feet to the SW Corner of a House

N40°E 84.37 feet to the SE Corner of a House

S25°E 39.77 feet to a nail in a Power Pole

N10°E 33.92 feet to a nail in a 12" Maple

N70°E 118.23 feet to a nail in a Power Pole

West2635.32'to the NW Corner Section 31

Shamelle -Signed by_ Surveyor's Michigan License No. 25859 Date

ssional Aug 11, 1997

Milletica

Land Surveyor No. 25859