

**SURVEY &
REMONUMENTATION**

DEC 16 1993

LIBER 1 PAGE 392

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

For corners in

<u>Sanilac</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>11N</u> R <u>12E</u>	<u>I - 13</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

RECEIVED FOR RECORD

93 DEC 13 AM 11:41

LIBER NO. 1 PAGE NO. 392
ESTHER LEE
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, John A Milletics, in a field survey on Aug 21, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I - 13 Found R/R Spike as recorded in Liber 4 Page 164 of the Sanilac County Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I - 13
SE Cor Section 34 T11N-R12E
Found Railroad Spike in blacktop

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I - 13
SE Cor Section 34 T11N-R12E
Set Monu Box
N45°E 83.18' to a nail in a Power Pole
N45°W 64.70' to a nail in a Power Pole
South 17.70' to the West Leg of a Arrow Sign

Signed by John A Milletics Date Nov. 4, 1993
Surveyor's Michigan License No. 25859