

REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Sanilac
(County)

Located In:

Corner Code =#

- 1. Public Land Survey T 11N R 13E M - 13, K - 13
T _____ R _____
T _____ R _____
T _____ R _____
- 2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
S _____ T _____ R _____
- 3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____
- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

RECEIVED FOR RECORD

93 DEC 17 PM 1:56

LIBER NO. 1 PAGE NO. 411
ESTHER LEE
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

Register of Deeds Stamp & File Number

I, John A Milletics, in a field survey on Aug 23, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M - 13 Found 5/8" iron bar in blacktop, per survey dated July 1989

K - 13 Found P.K. nail in blacktop, per survey recorded in Liber 4, Page 581 of the Sanilac County Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M - 13
SE Cor Section 36 T11N-R13E
Found 5/8" iron bar

K - 13
SW Cor Section 36 T11N-R13E
Found P.K. nail

SURVEY &
REMONUMENTATION

1993

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M - 13
SE Cor Section 36 T11N-R13E
Set Monu Box
N45°W 29.00' to the north end of a 42" CMP
N30°E 54.00' to a Tele Box
South 18.20' to the west leg of a Road Sign

K - 13
SE Cor Section 35 T11N-R13E
Set Monu Box
South 20.20' to the West leg of a Road Sign
N45°W 78.55' to a nail in a Power Pole
S45°W 100.85' to a nail in a Power Pole
West 2660.00' to the S 1/4 Cor Section 35

Signed by John A Milletics Date Dec 15, 1993
Surveyor's Michigan License No. 25859