For corners in

COMMISSION

2 PAGE 139 LIBER

REMOUNUMENTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

97 SEP - 9 AM 8: 58

IBER NO PAGE NO. L	39
REGISTER OF DEEDS SANILAC CO. MICHIGAN	
SANILAC CO. HICHIGAN	1

Sanilac (County)	Located In:	Corner Code #
(County)		
1. Public Land Survey	T <u>11NR1:</u> TR_	3E M -13
2. Property Controlling	TR_ TR_ S TR	- Dea 2
in Section 3. Miscellaneous	S TR_	
Property in Sec.	s tR_	

Register of Deeds Stamp & File Number

4. Lot No,	Recorded Plat
5. Private Claims _	

John A Milletics, in a field survey on June 21, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.

А 1 Г	B	_C	D	E	F	G	Н	I	J	ĸ	LN
2	<u> </u>		- 5 -	\downarrow	-4-	\downarrow	- 3-		-2-	1	-1
3 -		_		_		1		_			
4		_	- 8 - -	+	- 9-	_	-10 <u>-</u>	-	11-	-	-1 ₂
5	-	- -	\perp		+-	\bot	_	\perp	1_	\bot	
6 -	1 _, 8	+	 -1,7	\downarrow	-16	\bot	-1 _, 5	\perp	 14	1	 -13
7	-	+	- -	-	- -	-	_	-	\bot	-	
8	_1 ₉ _	-	-20_	+	-21_	+-	-22—	↓_	/ 23_	_	24—
9 _	-	- -	4_	1		╄		_	ļ	\perp	
10-	-30-	4	-29	\bot	-28	╀	_27 _ _	\vdash	 2 6	\bot	25
11	-	+	+	+	+-	+	-	╀	-	\bot	
12	-3 ¹ 1	+	32_	-	3 <mark>3</mark> _	+-	-34	 	35 <u>—</u>	-	36-
13						1	Ī				

A. Description of original monument and accessories and/or subsequent restoration:

M - 1.3

GLO Notes

E1m 24 N75°E 43

16 N75°W 15

Hemlock 10 N34°E 373

16 N75°W 15

Surveyor's Michigan License No. 25859

APPROVED PEER BOARD MEETING Aug 18, 1997 gm

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

SE Corner Section 36 T11N-R13E

Found Monu Box in place - removed by the Sanilac County Road Comm. during reconstruction of Road - Replaced using Act 74 as recorded in Liber Page 411

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: M - 13SE Corner Section 36 T11N-R13E MONU BOX with iron and cap South 18.20 feet to the West leg of a Road Sign S05°E 18.25 feet to the East leg of a Road Sign Milletics John A. Land Surveyor No. 25859 N15°W 39.88 feet to a Stop Sign N70°W 56.65 feet to a ROad Sign N30°E 54.00 to a Tele Box N45°W 29.00 feet to the North end of a 42" CMP so/onal Signed by Aug 11, 1997