

REMONUMENTATION CORNER

LIBER 1 PAGE 404

RECEIVED FOR RECORD

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

93 DEC 16 PM 2:04

For corners in

LIBER NO. 1 PAGE NO. 404
ESTHER LEE
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

Sanilac (County) Located In: Corner Code =#

1. Public Land Survey T 11N R 14E E - 13 D - 13
 T ___ R ___
 T ___ R ___
 T ___ R ___

2. Property Controlling S ___ T ___ R ___
 in Section S ___ T ___ R ___ Seg 1
 3. Miscellaneous S ___ T ___ R ___
 Property in Sec. S ___ T ___ R ___

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, John A Miletics, in a field survey on Aug 23, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E - 13 Found Monu Box in centerline of M-19 and the Marlette Road, per State Highway R/W Book and survey dated June 1982

D - 13 Found Rail Road Spike 6.90 south of blacktop centerline, as per survey dated June 1985 and consistent with Sanilac County Road Comm records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E - 13
SE Cor Section 32 T11N-R14E
Found Monu Box

D - 13
S 1/4 Cor Section 32 T11N-R14E
Found Railroad Spike

SURVEY &
REMONUMENTATION

1993

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E - 13
SE Cor Section 32 T11N-R14E
Found Monu Box

D - 13
S 1/4 Cor Section 32 T11N-R14E
Found Rail road spike

S80°W 54.25' to a concrete right of way marker Set Monu Box
 N45°W 67.85' to a nail in a Power Pole North 49.85' to a nail in a 24" ash
 S80°E 61.60' to a concrete right of way marker N30°E 47.20' to the east end of a 12" CMP
 East 2652.00' to the SE Cor of said Section

Signed by John A Miletics Date Dec 15, 1993
 Surveyor's Michigan License No. 25859