NOV 2 1 1997

LIBER

REMOUNUMENTION

2 PAGE 143

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

97 SEP -9	AM 8	3: 58
LIBER NO STHE REGISTER	AGE N	0. MZ
REGISTER	R LEE OF DEE	DS

For corners in Sanilac Located In.

Corner Code #

SANILAC CO., MICHIGAN

1. Public Land Survey

2. Property Controlling in Section 3. Miscellaneous Property in Sec.

T 11NR14E

Register of Deeds Stamp & File Number

, Recorded Plat 5. Private Claims

John A Milletics, in a field survey on June 21, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.

1	<u>A</u>	В	С	D	E	F	G	н	I	J	ĸ	L N
	1			T		Т	T		Т	Т	T	П
2		6-	+-	5-	十	4-	+	- 3	+	2	+	i
3	-	+-	-	┼	-	╄-			1	-	+	ļ
4	\vdash	7	+-	8	-	9	+	-1 ₀ —	<u> </u>	1 11—	 	 12—
5	-	╁	-	}	ļ	╄	ļ	+	-	_	-	_
6	-	i, <mark>e—</mark>	_	i'—	 3	1 L6—	_	ا -15	<u> :</u>	 14—	1	ا 13—
7	┕	╄-	_	_		<u> </u>	<u> </u>	<u> </u>		<u> </u>		
В	1	ا وي	 	 20—	<u> </u>	21_	1_	-22_	<u>_</u> ;	 ?3	\perp_2	 24
9			_	igspace	_		<u> </u>		<u> </u>	_		
10	<u> </u> ;	[30—	<u> </u> _;	ا وا	<u> </u> _;	 28	_	.27 <u>—</u>	<u>_</u> 2	 ≥6	_2	 5
11	<u> </u>	<u> </u>	_	_	L		_	_	L	L.		
	١,		١,	 2	Ι,	[:3].	١.	Ļ	1 _	
12		 	Τ,	,, 	厂 ³) 	1	34 1	-3	15—- I	13	6—
12		1	L	Ι.	_	1	ı	i	I	I	1	1 1

A. Description of original monument and accessories and/or subsequent restoration:

E - 13

GLO NOTES

Beech

9 N76°W 33

Sugar Maple 24 N43°E 24

APPROVED PEER BOARD MEETING

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Monu Box in place - removed by the Sanilac County Road Comm. during reconstruction of Road - REPLACED by using Act 74 as recorded in Liber 1 Page 404

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Millimilliming

E - 13

SE Corner Section 32 T11N-R14E

 ${\tt MOUN~BOX~with~iron~and~cap}$

\$80°W 54.25 feet to a concrete right of way marker

N45°W 67.85 feet to a nail in a Power Pole

S80°E 61.60 feet to a concrete right of way marker

S45°E 60.53 feet to a nail in a Power Pole

N45°E 70.85 feet to a nail in a Power Pole

 $S45^{\circ}W$ 55.55 feet to a riser box

Signed by <u>C</u>

Surveyor's Michigan License No. 25859

Date Aug 11, 1997

John A. Milietic Land Surveyor No. 25859

Milietics