

REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Sanilac (County) Located In: Corner Code #/

1. Public Land Survey	T 11N R 14E	I - 13, G - 13
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

RECEIVED FOR RECORD

93 DEC 29 AM 10:55

LIBER 1 PAGE NO. 430
 ESTHER LEE
 REGISTER OF DEEDS
 SANILAC CO., MICHIGAN

Register of Deeds Stamp & File Number

I, John A Milletics, in a field survey on Dec 17, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2								
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I - 13
 Found 1/2" iron in centerline of paved surface

G - 13
 Found Railroad Spike in centerline of paved surface, per survey recorded in Liber 3 on Page 583 of the Sanilac County Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I - 13	G - 13
SW Cor Section 35 T11N-R14E	SW Cor Section 34 T11N-R14E
Found 1/2" iron bar	Found Railroad Spike

SURVEY &
 REMONUMENTATION

1993

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I - 13	G - 13
SW Cor Section 35 T11N-R14E	SW Cor Section 34 T11N-R14E
Set Monu Box	Set Monu Box
N45°E 76.20' to a nail in a Power Pole	South 19.10' to the East Leg of a Road Sign
S45°E 73.55' to a nail in a Power Pole	N20°W 111.40' to a nail in a 8" Maple
South 18.30' to the East Leg of a Road Sign	N45°W 81.00' to a nail in a Power Pole

Signed by John A Milletics Date Dec 24, 1993
 Surveyor's Michigan License No. 25859