

1993

LIBER

1 PAGE 439

REMONUMENTATION
COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Sanilac</u> (County)	Located in:	Corner Code #
1. Public Land Survey	T <u>11N</u> R <u>15E</u>	<u>D - 13</u> C - 13
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

RECEIVED FOR RECORD

93 DEC 29 AM 11:03

1993
REGISTER OF DEEDS
SANILAC CO. MICHIGAN

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, John A. Millettics, in a field survey on Oct 15, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therofore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2								
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- D - 13
Found 1/2" iron bar in gravel road bed, per survey dated 2-13-1980
 - C - 13
Found Monu Box in centerline of paved surface, per survey dated 2-13-1980

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- | | |
|--------------------------------|-----------------------------|
| D - 13 | C - 13 |
| S 1/4 Cor Section 32 T11N-R15E | SW Cor Section 32 T11N-R15E |
| Found 1/2" iron bar | Found Monu Box |

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- | | |
|---|--|
| D - 13 | C - 13 |
| S 1/4 Cor Section 32 T11N-R15E | SW Cor Section 32 T11N-R15E |
| 1/2" iron bar | Monu Box |
| N55°E 107.14' to a nail in a Power Pole | N45°E 60.20' to a nail in a Power Pole |
| N60°W 41.25' to a nail in a Mail Box Post | N50°W 80.20' to a nail in a Power Pole |
| N55°W 105.20' to a nail in a Power Pole | S10°E 61.15' to a nail in a Power Pole |
| West 2653.45' to the SW Cor Section 32 | |

Signed by John A. Millettics Date Dec 24, 1993
Surveyor's Michigan License No. 25859