

For corners in COMMISSION

Sanilac
(County)

Located In:

Corner Code ##

- | | | |
|------------------------------------|---------------------------|-----------------------|
| 1. Public Land Survey | T <u>11N</u> R <u>15E</u> | <u>H - 13, G - 13</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |

RECEIVED FOR RECORD

93 DEC 29 AM 10:55

LIBER 1 PAGE NO. 432

ESTHER LEE
REGISTER OF DEEDS
SANILAC CO. MICHIGAN

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, John A. Milletics, in a field survey on Oct 13, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|----|----|----|----|----|---|---|---|---|---|---|---|
| 2 | 6 | 5 | 4 | 3 | 2 | 1 | | | | | | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | 8 | 9 | 10 | 11 | 12 | | | | | | | |
| 5 | | | | | | | | | | | | | |
| 6 | 13 | 17 | 16 | 15 | 14 | 13 | | | | | | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | 20 | 21 | 22 | 23 | 24 | | | | | | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | 29 | 28 | 27 | 26 | 25 | | | | | | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | 32 | 33 | 34 | 35 | 36 | | | | | | | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

- H - 13
Found 1/2" iron bar in gravel Road Bed, per survey dated 7-13-84 showing iron set over plow point
- G - 13
Found 5/8" iron bar in gravel road bed, per Irvin E Chope Survey

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- | | |
|--------------------------------|-----------------------------|
| H - 13 | G - 13 |
| S 1/4 Cor Section 34 T11N-R15E | SW Cor Section 34 T11N-R15E |
| Found 1/2" iron bar | Found 5/8" iron bar |

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- | | |
|--|---|
| H - 13 | G - 13 |
| S 1/4 Cor Section 34 T11N-R15E | SW Cor Section 34 T11N-R15E |
| 1/2" iron bar | 5/8" iron bar |
| North 35.55' to a nail in a 18" Maple | N45°W 39.95' to a Stop Sign |
| N50°W 72.10' to a nail in a 12" Ash | S30°W 19.35' to the East Leg of a Road Sign |
| N70°E 56.70' to a nail in a 10" Ash | N45°W 40.00' to the North End of a 12" CMP |
| East 2670.64' to the SE Cor Section 34 | S45°W 40.30' to the South End of a 12" CMP |

Signed by John A. Milletics
Surveyor's Michigan License No. 25859

Date Dec 24, 1993