

1993
REMONUMENTATION
COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Sanilac</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>11N</u> R <u>15E</u>	<u>J - 13, I - 13</u>
	T ___ R ___	_____
	T ___ R ___	_____
	T ___ R ___	_____
2. Property Controlling in Section	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

RECEIVED FOR RECORD
93 DEC 29 AM 10:55
LIBER NO. 1 PAGE NO. 433
ESTHER LEE
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

Register of Deeds Stamp & File Number

I, John A Millettis in a field survey on Oct 15, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

- J - 13
Found 1/2" iron bar in gravel road bed, per survey dated 10-6-85
- I - 13
Found 1/2" iron bar in gravel road bed, per survey dated 7-13-84

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- | | |
|--------------------------------|-----------------------------|
| J - 13 | I - 13 |
| S 1/4 Cor Section 35 T11N-R15E | SW Cor Section 35 T11N-R15E |
| Found 1/2" iron bar | Found 1/2" Iron Bar |

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- | | |
|---|--|
| J - 13 | I - 13 |
| S 1/4 Cor Section 35 T11N-R15E | SW Cor Section 35 T11N-R15E |
| 1/2" iron bar | 1/2" iron bar |
| N70°E 94.65' to a nail in a 18" Ash | N45°W 67.25' to a nail in a 24" Ash |
| N50°E 47.35' to a nail in a Tele Pole | N55°E 52.55' to a nail in a Fence Post |
| South 21.20' to the West leg of a Road Sign | S45°E 32.70' to a nail in a Power Pole |
| N30°W 37.70' to a Stop Sign | S10°W 27.00' to a nail in a 10" Ash |

Signed by John A Millettis Date Dec. 24, 1993
Surveyor's Michigan License No. 25859