

1993

LIBER 1 PAGE 414

RECEIVED FOR RECORD

93 DEC 28 AM 10:39

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

For corners in

LIBER 1 PAGE NO. 414
ESTHER LEE
REGISTER OF DEEDS
SANILAC CO. MICHIGAN

Sanilac (County) Located In: Corner Code #

1. Public Land Survey T 11N R 16E H - 13, G - 13
 T R
 T R
 T R

2. Property Controlling S T R
 in Section S T R

3. Miscellaneous S T R
 Property in Sec. S T R

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, John A Milletics, in a field survey on Oct 11, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefor as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

H - 13

Found 5/8" iron bar in gravel road bed, per survey recorded in Liber 2, Page 380 of the Sanilac County Records.

G - 13

Found 1/2" iron bar in gravel road bed, per survey recorded in Liber 3, Page 235 of the Sanilac County Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H - 13

S 1/4 Cor Section 34 T11N-R16E
 Found 5/8" iron bar

G - 13

SW Cor Section 34 T11N-R16E
 Found 1/2" iron bar

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H - 13

S 1/4 Cor Section 24 T11N-R16E
 5/8" iron bar
 N40°E 51.35' to a nail in a Power Pole
 N30°E 47.05' to a nail in a Power Pole
 N70°W 54.50' to the east leg of a Road Sign
 West 54.53' to the NW Cor Section 1

G - 13

SW Cor Section 34 T11N-R16E
 1/2" iron bar
 North 33.00' to a iron bar
 S30°E 40.70' to a nail in a cor fence post
 S10°W 77.15' to a nail in a 18" Apple

Signed by

John A Milletics

Date

Dec. 24, 1993

Surveyor's Michigan License No.

25895