i i	1
TE IVIC	MUNICIPALL

JAN 1 9 2000

LIBER 2 PAGE 337

SECTION

Surveyor's Michigan License No.

1999 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich. P. A. 1970

RECEIVED FOR RECORD

SO IS MY OF AUN BE

For corners in	Fili	ing Requirement of Act 74, Mich	h. P.A. 1970	of Yun ee	
				LIBER NO. 2	PAGE NO 33
SANILAC (County)	Located In:	Corner Code #		10001111114	SHOUNTAN
1. Public Land Survey	T12ND	1117		REGISTER SANILAC CO	MICHIGAN
r. Public Land Survey	T <u>12</u> NR T R				
	T R				
2. Property Controlling	TR				
in Section	S TR				
3. Miscellaneous Property in Sec.	s TR				
Froperty in Sec.	S IR	<u> </u>	R	Register of Deeds St	amp & File Num
4 Lathia B	1.15				
5. Private Claims	rded Plat		, A	BCDEFO	зні јк
			2		
			3		32
, John A. Milletics	, in a field survey on	Aug. 2, 19 99 do hereby state t	that under	-7	-1011
requirements of P.A. /4, Michiga	In P.A. of 1970, the com	er points mentioned in lines 1 and 2 aboved in the current manual of survey instruction	ve umre in		
United States Department of the I	interior. Bureau of Land M	fanagement or by a decree of a Court of La	aut and for	18 17 16	
Soard of Land Surveyors or by	a Decree of a Court o	were in conformance with the rules of the of Law; established, re-established, mon	Michigan		
recovered, found as expressed be	low:	, , , , , , , , , , , , , , , , , , , ,	в —	-192021	2223
NOTE: Not more than 2 com	iers, all in the same tow	n and range, may be recorded	9		
on this certificate.			10	302928	2726
			11	 	
			12	31-32-33-	3435
Description of original mor	nument and accessori	es and/or subsequent restoration;	13		
-7 Tamk. 10 S16W 13 O <u>l</u> d Survey Libe		!5W 22			
Act 132 - None	r wone				
Unrecorded surv	ey - Milletics	dated Sept 1982			
L.C.R.C None					
. Description of corner evid	ence found and/or me	thod applied in restoring or reestablis	shing corner:		
7					
SW Corner Section Found 5/8" Iron B	18, Tl2N-R14E	in Blackton			
North 2635.22 fee	t to the W 1/4	Corner			
South 2652.20 fee	t to the W 1/4	Corner			
Accepted as best	evidence		APPROV	ED PEER BOARD	MEETING
			NOV 19	,1999	THELING
				gn	
. Description of monument for	or corner and accesso	ries established to perpetuate locating	a the position of	the corner	188424
A - 7		•	2 p		
SW Corner Section		• .		Property of the second	
5/8" Iron bar in North 2635.22 fee	Monu Box in Bla t to the W 1/4	acktop Corner			
South 2652.20 fee	t to the W $1/4$	Corner		The State of the S	
N40°W 55.37 feet	to the SE Corne	er of a Bell Riser Box		entill (learn of more to point to	
N30°W 43.82 feet	to a Stop Sign	D 11			
N30°E 62.40 feet S45°E 66.12 feet	to a nail in a	rower Pole			1. · · · ·
C30°E 42 60 fast		TOMET TOTE		The same	1

11-15-1999

Date