MAY 0 7 1997 LIGER

2 PAGE 106

COMMISSION

REMONUMENTION

RECEIVED FOR RECORD

. B . . Welvery

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 For corners in

96 DEC 10 AM 11: 56

LIBER NO. 2 PAGE NO. 106 ESTHERLEE REGISTER OF DEEDS SANILAC CO. MICHIGAN

Sanilac Located in: Corner Code # 1. Public Land Survey T13NR 12E 2. Property Controlling in Section 3. Miscellaneous Property in Sec.

Register of Deeds Stamp & File Number

4. Lot No. \_ , Recorded Plat 5. Private Claims

I, John A Milletics, in a field survey or Aug 10 , 19 96 do hereby state that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded

1 A B C	D 1	E F	G H	ΙJ	KLN
2 - 6-	-5-				T
3			LĬ	T-1-	1-1-
4 - 7 -	_   _				†
5	_ Ĭ	ر آ	10 	11-	12-
			- -	<del>  </del>	┟┈╁╼┤
6 18	-17-1	-16	15	14	-13
8 19				┯╉╼┧	
1 7 1	-20-	-21	22	—2 <sup>1</sup> 3—	24
9	╅	╼┟╼╼╅		╼┼╼┤	
10 30	~29—	-28	-27	-2 <del>6</del>	_25
11	┤╼┼	╅┯╂			
12 31-	-32	-33	_34	35	-36
13				_L. l	Ĭ

A. Description of original monument and accessories and/or subsequent restoration: E-13 GLO Notes

80.00 Set Post Corner B. Ash 14 N62W 23 7 N80E 6 Birch

No Old Survey Liber No Act 74, No Act 132

F-13 CLO Notes

40.00 Set 1/4 Section Post Beech 12 N53E 34

No Old Survey Liber No Act 74, No Act 132

Beech 10 N3912W 32

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

SW Corner Section 33 T13N-R12E Found 1/2" Iron Bar in Gravel Road Bed

F-13

S 1/4 Cor Section 33 T13N-R12E Found 1/2" Smooth Iron Bar in Gravel Road Bed APPROVED PEER BOARD MEETING 12-02-86 97

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: E-13

SW Corner Section 33 T13N-R12E 1/2" Iron Bar in gravel Road Bed West 9.85 feet to a 1/2" Iron Bar S45°W 52.55 to a nail in a Power Pole N45°W 50.15 to a nail in a Tele Riser West 2628.58 to the S 1/4 Cor East. to the S 1/4 Cor

S 1/4 Corner Section 33 T13N-R12E 1/2" Smooth Iron Bar in Gravel Road Bed

West 22.30 to a T Bar

S50°W 31.60 to a nail in a Fence Post

NIO°W 54.70 to a nail in a 6" Oak

to the SW Cor

East

to the SE Cor

Signed by Surveyor's Michigan License No.

Nov 15, 1996 Date

John A. Milletics Land Surveyor No. 25859 ~0

William of W.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSION