WAY - 7 1987 HEER

=2 page 92

RECEIVED FOR RECORD

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

96 DEC 10 AM 11: 55

| LIBER NO. 2 PAGE NO. 92 |
|-------------------------|
| |
| REGISTER OF DEEDS |

| For | corners | in |
|------|---------|-----|
| 1 01 | | 111 |

4. Lot No. .

5. Private Claims _

| | Sanilac ' | Located in: | Corner Code ## | REGISTER O |
|----|----------------------|-------------|----------------|------------------------|
| | (County) | | | SĂNILAC CO. |
| 1. | Public Land Survey | T 13N R14E | (F-13), G-13 | , |
| | · | T R | | |
| | | T R | | |
| | • | T R | | |
| 2. | Property Controlling | S T R | | |
| | in Section | S T R | | |
| 3. | Miscellaneous | S T R | | Register of Deeds Star |
| | Property in Sec. | S T R | | |

mp & File Number

| | | 3 |
|--|--|---|
| John A Milletics , in a field survey on _ | June 1, | 19 96 |
| do hereby certify that under requirements of P.A. 74, Mic in lines 1 and 2 above were in conformance with regu current manual of survey instructions of the United Sta | higan P.A. of 1970, the dations and rules ther des Department of the | corner points mentioned efore as required in the Interior, Bureau of Land |
| Management or by a decree of a Court of Law and/or tha above were in conformance with the rules of the Michig Court of Law; established, re-established, monume | an Board of Land Surve | eyors or by a Decree of a |

___ , Recorded Plat __

expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10

A. Description of original monument and accessories and/or subsequent restoration:

F - 13 GLO NOTES 40.00 Set 1/4 Section Post Tamarack 7 N59W 72

NO Survey in Old Liber Unrecorded Survey dated 9-91 Total Section Run Act 74 None, Act 132 None

Tamarack 9 N45E 17 No Road or Drain Comm. Records

G - 13 GLO NOTES 80.00 Set Post Corner Beech 9 N811E 26 Cedar 7 N29 W 21

NO Survey in Old Liber Unrecorded survey dated 9-91 Total Section Run Act 74 None, Act 132 None No Road or Drain Comm Records

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

S 1/4 Corner Section 33 T13N-R14E Found 1/2" Iron Bar in Gravel Road Bed half way between SE and SW Corners

G - 13

SE Corner Section 33 T13N-R14E Found 1/2 Iron Bar in Gravel Road Bed

APPROVED PEER BOARD MEETING 12-02-96 97

| C. | Description of monument for corner and | accessories established to perpetuate | locating the position of the corner: |
|----|--|---------------------------------------|--------------------------------------|
| 44 | 10 | C = 13 | |

S 1/4 Corner Section 33 Tl3N-R14E 1/2" Iron Bar In Gravel Road Bed SO5°E 31.60 to a nail in a bell box post SO5°W 86.87 to a nail in a 36" Maple N60°W 97.30 to a nail in a Power Pole West 2649.08 feet to the SW Cor Section 32 West 5.28 to a 1/2"iron Bar N 1/4 Corner Section 4

SE Corner Section 33 T13N-R14E 1/2" Iron Bar in Gravel Road Bed S45°E 49.08 to a nail in a bell pole N50°E 84.40 to a nail in a power pole N40°W 67.91 to a nail in a power pole S45°W 47.06 to a nail in a fence post

____ Date _

West 2649.08 to the S 1/4 Corner Section Halling

Aug 3, 1996

As John A. Millatics Land Surveyor -No. 25336

William Will

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN REVISED MAY 70,310 Bal REVISED, MAY 44

Surveyor's Michigan License No. ____

25859