SURVEY & REMONUMENTATION

MAD T & 1000

ST. CLAIR COUNTY, MICHIGAN OFFICIAL GOVERNMENT CORNER

mare as significant	0111001= 0011				20	
SECTION		CORDATION CERTIFICAT of Act 74, Mich. P.A. 1970				
	Located In: Clay Township	Corner Code #		34 O X	1	FEOI
Public Land Survey Property Controlling S in Section S Miscellaneous S Property in Sec. S	TR	C-11	Register of	Deeds Stamp	ES STILL NO.	Imber Imber
1970, the corner points me with regulations and rules instructions of the United Management or by a decimentioned in lines 3, 4 an Michigan Board of Land	, in a field survey on Authat under requirements entioned in lines 1 and 2 therefore as required in the States Department of the cree of a Court of Law and 5 above were in conford Surveyors or by a Definition on the conformal conformal surveyors or by a Definition of the conformal conf	of P.A. 74, Michigan P.A. of above were in conformance the current manual of survey he Interior, Bureau of Land and/or that the corner points rmance with the rules of the becree of a Court of Law; imented, recovered, found as	A B C 2 6 3 4 7 5 6 18 7 8 19 9 10 30 11 12 31	D E F G -5 -48917162021292832333233	151	K L N
A. Description of original	monument and accesso	ries and/or subsequent restor	ation:			
Certificates have been record 3/4" iron pipe (undated). Ear 1" diameter pipe in survey ar	led for this corner. Old Courl Phillips referenced corner and field notes dated October	ns 29, 30, 31 and 32 on a Poplar T inty Surveyors Record lists a ston r in survey dated Nov. 3, 1949. V r 13, 1969. Herbert Kobs found a dated August 3, 1971. Robert Ku	te with an "X" alentine-Thor 1/2" iron pip	' mark (undat mas recovere e during surv	ed) and d and w ey dated	a found itnessed a d Februar

April 28, 1980, see Liber 7 of Surveys, page 388. John Fenn recovered and witnessed a 3/4" iron pipe on a survey dated March 23, 1994. Jerry James references corners as a found iron bar in a survey dated Nov. 7, 1995, see Liber 15 of Surveys, page 268.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a 1/2" diameter rebar with illegible caps set over (at bend point) a bent 1" diameter iron bar at the approximate centerline of Starville Road (gravel) and Clay Road (not maintained). Verified corner using previously recorded and unrecorded witnesses. Checked distance to 1/4 corner common to Sections 29, and 30, 2707.57' (R), 2707.39' (M). Checked distance to 1/4 corner common to Sections 30 and 31, 2771.0'(R) 2770.6'(R), 2770.57'(M). Checked distance to found 3/4" iron pipe at the intersection of Starville Road and Holland Road, 1789.71'(R), 1789.38'(M).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set a 2" diameter aluminum cap with a magnet, inscribed "St. Clair County Official Corner, placed on a 1/2" diameter iron rerod approximately 4" below gravel road surface, on the approximate centerline of Starville Road (gravel).

S 19°W 78.75' to a set P.K. nail with S.C.C. Remon. washer in S.E. side of Power Pole.

N 56°W 43.97' to a set P.K. nail with S.C.C. Remon. washer in N.E. side of Power Pole.

S 82°E 45.08' to a set P.K. nail with S.C.C. Remon washer in S. side of 12" Pine Tree.

N 16°E 84.99' to a set P.K. nail with S.C.C. Remon. washer in N.W. side of Telephone Pole.

S 80°E 32.87' to the centerline of a 4" well casing.

				APPART L' DEC. 15, 19		
	1 1					
Signed by	u\(\tau\)		Date Dec	enley 4, 1998		
Surveyor's Michigan License No.	24608		- 1			