

ST. CLAIR COUNTY, MICHIGAN OFFICIAL GOVERNMENT CORNER



LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

	Located In:	Corner Code #
	Columbus Twp.	
1. Public Land Survey	T <u>5N.</u> R <u>15E.</u>	<u>M-1</u>
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	<u>Seg. #1 pm</u>
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

REGISTERED OF DEEDS
ST. CLAIR COUNTY

RECEIVED
1993 DEC 29 AM 9:00

Register of Deeds Station & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, John R. Lansky in a field survey on Sept. 14-18, 1993
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

NOTE: Not more than 1 corner, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1. 3" Ironwood-- Per Original Gov't Survey.
2. Conc. Monument 1936 (Per County Rec.)

STATE PLAIN COORDINATES

N. _____

E. _____

ELEVATION _____

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Conc. monument with iron rod inserted to be raised 6" to surface. 2159A000 12/29/93MSSU7 11.00
0001

Note: This Monument agrees with location on certificate filed by RLS 12033 as recorded in L. 1 P.773 2159A000 12/29/93SSRE7 2.00
0001

This Corner is Common to Four Townships and certificates are being filed for each township.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Concrete Monument (With Iron Rod inserted)

- N.W. 43.57 Set PK nail with County Tag in D.E. Pole
- N.E. 67.8 to center of Sun Pipe line marker.
- S.E. 77.4 to N.W. Corner of N/S. Conc. Headwall
- S.W. 77.7 to N.E. Corner of N/S. Conc. Headwall

Note: Found Iron Rod 4.27 ft. SE.'ly (Road P.I) ref. AD Plat No. 53 and 106.



Signed by John R. Lansky Date Sept. 20, 1993
Surveyor's Michigan License No. 18659

PA 345-1990
PEER COMMITTEE

APPROVED 11-30-93

APPROVED AS AN OFFICIAL GOVERNMENT CORNER BY ST. CLAIR COUNTY:

Signed By: _____ Date _____

St. Clair County Land Surveyor

Surveyor's Michigan License No. _____