## **SURVEY & REMONUMENTATION**

JAN 31 2001

SECTION
---------

LAND CORNER RECORDATION CERTIFICATE BER 6 PAGE 19 Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN ST. JOSEPH COLWTY FILED

For corners in Park Township

Corner Code # Located In: St. Joseph County (County) 1. Public Land Survey D-8 R\_11W T 58 S<u>20</u> 2. Property Controlling in Section 3. Miscellaneous Property in Sec.

29 MAR 2000 10:12:54 AM

CYNTHIA L. JARRATT REGISTER OF DEEDS


Register of Deeds Stamp & File Number

4. Lot No	, Recorded Plat	 		
5. Private Claims		 		_

\_in a field survey on <u>March 8</u> \_ 20\_00\_do state that under requirements of P.A. 74, Michigan David W. Mostrom P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a degree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, reestablished, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

(D-8) CENTER SECTION 20, PARK TOWNSHIP



A. Description of original monument and accessories and/or subsequent restoration:

1972 SAYERS SURVEY

CORNER NOT LABELED OR WITNESSED

1973 KESTER SURVEY

3/4" PIPE IN MONUMENT BOX

1983 MOSTROM SURVEY FOUND 3/4" PIPE IN MONUMENT BOX 12" HICKORY = \$47°E 43.80" 16" HICKORY = S87°E 41.47'

P. POLE = N77°W 35.18'

1999 MOSTROM SURVEY

FOUND 1" PIPE 12" DEEP IN GRAVEL ROADWAY

16" HICKORY = \$47°E 43.80" 22" HICKORY = \$87°E 41.47' 50" TRIPLE OAK = N45°E 44.83' P. POLE = N83°W 35.18'

ROAD COMMISSION (NO DATE) THIS CORNER WAS DUG

FOR BY HAND BUT NOT FOUND

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1" PIPE 14" DEEP IN MONUMENT BOX IN CENTERLINE OF BUCKHORN ROAD 16" HICKORY = \$47°E 43.80' 22" HICKORY = \$87°E 41.47" 50" TRIPLE OAK = N45°E 44.83' P. POLE = N83°W 35.18' CORNER FALLS IN LINE WITH FENCES TO THE EAST & WEST CORNER FALLS 0.65' NORTH & 0.09' EAST OF INT. OF 1/4 LINES SET 5/8" X 24" IRON BAR WITH STD, CAP IN 1" PIPE IN MONUMENT BOX



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 24" IRON BAR WITH STD. CAP IN MONUMENT BOX N & W IN SE SIDE OF 50" TRIPLE OAK = N45°E 44.83' N & W IN N. SIDE OF 22" HICKORY = S87°E 41.47' N & W IN SW SIDE OF 16" HICKORY = \$47°E 43.80" N & W IN S. SIDE OF P. POLE = N83°W 35.18' N & W IN S. SIDE OF P. POLE = S71°E 58.52'

RATIFIED BY PEER GROUP IN/ACCORDANCE WITH P.A. 345 ON MARCH 13 ,2000 UMen. CO. REPRESENTATIVE

Signed by_	VQ.	JM	t

David W. Mostrom

Date\_\_\_ March 23, 2000

32339 Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 18, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983