NOV 3 0 1993

## 004 N 008

FILED

COMMISSION

corners in

ressed below:

on this certificate.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

JUL	27	- 1	^>	DH	101
JUL	U	- 1	רח	1/14	٠4.

ST. JOSEPH	Located In:	Corner Code :##	Cypthin R. Lanatt
FLOWERFIELD TW Public Land Survey	IP. т 55 в 12W	K-6	REGISTER OF DEEDS ST. MISERH OF MICH
Public Land Sulvey	T R		
Property Controlling	T R		V
in Section Miscellaneous	S T R S T R		Register of Deeds Stamp & File Number
Property in Sec.	S T R	,	
	BOOTGE THAT		
WAYNE A. MOSTROM.	, in a field survey on	, 19 <b>9.3</b>	4 7 8 9 10 11 12
nereby certify that under reques 1 and 2 above were in	uirements of P.A. 74, Michigan P.A. n conformance with regulations an uctions of the United States Depar	of 1970, the corner points mentions of rules therefore as required in the	ed 6 18 17 16 15 14 13 13 15

Description of original monument and accessories and/or subsequent restoration:

TE: Not more than 4 corners, all in the same town and range, may be recorded

ragement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 ve were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a art of Law; established, re-established, monumented, re-monumented, recovered, found as

.C.R.C.-1986 BY MDOT GLO 1964 MDOT 36" W.O.=540°E 45 LKS 18" W.O.=N33°W 27 LKS PIPE OVER STONE IN BOX ROD IN MON BOX 29" CHERRY=N7°E 193.9" 7" PINE = N50'E 62.9' SW COR HSE = N60°E 109.93'
7" PINE = N85°E 47' 19" CHERRY=514°W 90.93" 1972 BY SAYERS COR IS 2'E RDWY SHOWS MON BOX & PIPE 2663.711 7" PINE = \$30°E 105.35° L.C.R.C.-3/32-1976 S. & 2658.88' N OF COR'S TO 1993 SURVEY BY HUNT-677/433 BAR IN MON BOX STAKE = \$45°W 40' STAKE = \$45°E 40' 1" ROD IN MON BOX IN CL. RDWY. ROAD COMMISSION-1960'S 5/8" ROD = EAST 33" in PIPE OVER LARGE +1D STONE 29" CHERRY=N7°W 193.9' TEL. RISER = N30°E 51' & S20°E 99.9' SW COR HSE = N45°E 110.10' STAKE = N45°W 40' 19" CHERRY=\$14\*W 90.931

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND IRON BAR IN MON BOX OVER STONE 24" DEEP SW COR HOUSE = N45°E 110.10' IRON BAR = EAST 33' & ROAD = EAST 1.7 CHECKED TO TELE. RISERS ON 1993 SURVEY O.K.

ROAD AS BEEN IMPROVED - ALL OLD TREES WERE REMOVED NOTE:

f il

Description of monument for corner and accessories established to perpetuate locating the position

WEST 1/4 COR SEC. 13

SET 5/8"X24" BAR W/STD. CAP OVER LARGE STONE IN MON BOX IRON ROD = EAST 33.02'

NW COR GARAGE FTDN = N40°E 154.701

SW COR HSE FTDN = N45°E 110.10'

€ RDWY = EAST 1.7'

TELE. RISER = N30°E 51.30' £

TELE. RISER = \$20°E 99.9'

14100 zeyor's Michigan License No. \_\_\_

Date JULY 15, 1993

10

11

12

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

A STATE OF THE PARTY OF THE PAR OF MIONS

WAYME A

COMPETAGM

PROFESSIONAL

SURVEYOR

No.

14100

OFE SSION

STATE

LICENSTID

REVISED JAN., 1983

7 3113