	•	END CONTENT RECORDANCE CENTRICATE		
For corners in	APR 1 0 1995	Filing Requirement of Act 74, Mich. P.A. 1970IBER 4	PAGE 98	

For corners in APR 10	1995 Ima reduit	silient of Act 14, witch, F	A. 197 YIBER T PAGE 7U
ST. JOSEPH COUNTONNO COLON TWP.	SSIONLocated In:	Corner Code ##	STATE OF MICHIGAN ST. JOSEPH COUNTY
1. Public Land Survey	T <u>6S</u> R <u>9W</u>	I – 5	FILED
·	T R T R		23 JAN 95 9:21 A.M.
	T R		CYNTHIA JARRATT
2. Property Controlling			· · ·
in Section	S T R		REGISTER OF DEEDS
3. Miscellaneous	S		Register of Deeds Stamp & File Number
Property in Sec.	S T R		
	ecorded Plat		

NOVEMBER 29 19 94 I,DAVID W. MOSTROM in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(I-5) CORNER COMMON TO SECTIONS 10, 11, 14, 15 1862 SURVEY BY N.S. ANDREWS 1933 SURVEY IN BK B, PG. 550 STONE SET FROM OLD WIT. STUMP + STONE 1903 € 1904 SURVEYS IN BOOK B,PG 104 € 2 WITNESSES OUT BOOK 1, PG. 77 & BOOK 1, PG 99 MDOT (NO DATE) + STONE 2 WITNESSES OUT

FD. + STONE - RAISED W/5/8" IRON & BOX

NE HSE COR = \$30°E 105.72¹

NW HSE COR = \$18°E 88.85¹

HWY CL = NORTH 6.85!

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(1-5)FOUND 5/8" REBAR IN MON. BOX 6.8' SOUTH OF HWY. CL MAIL BOX = NE 55' 4 WITNESSES FROM 1992 L.C.R.C. CHECK OK

> RATIFIED BY PEER GROUP IN ACCORDANCE WITH P.A. 345 Dec. 12 . 1994 _CO. REPRESENTATIVE

1974 LCRC IN BK 1, PG 97

& 1974 SAYERS SURVEY PIPE IN MON. BOX MAILBOX = NE 55'CL HWY = NORTH 6.8' 1992 LCRC IN BK 3, P-229 FD 5/8" REBAR IN MON BOX 6.8' S. OF HWY CL PP = N01°E 39.08' TELE. RISER BOX = N63°E 107.40

TELE. RISER BOX = \$25°W 41.03 N. LEG SIGN POST = S80°W

78.251



C. Description of monument for corner and accessories established to perpetuate locating the position of the co-

(1-5) CORNER COMMON TO SECTIONS 10, 11, 14, 15 SET 5/8"X 24" IRON BAR/STD. CAP IN MON. BOX 6.8' SOUTH OF HWY. CL N & W 2' HIGH ON W. SIDE OF PP. = N05°W 39.09' N & W 2' HIGH ON NE SIDE OF PP. = \$60°E 106.70 NE HSE CORNER (FOUNDATION) = \$30°E 105.72' NW HSE CORNER (FOUNDATION) = S18°E

Signed by

Date DECEMBER 14, 1994

Surveyor's Michigan License No. 32339

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

REMONUMENTATION