JAN 1 7 1996 LAND CORNER RECORDATION CERTIFICATE

_	Filing Requireme	ent of Act 74, Mich. P	ر A. 1970 م		4.6	,			
For corners in COMMISSIO ST. JOSEPH COMMISSIO	N ed In:	Corner Code #	LIBER 4	PAGE	18	נ			
NOTTAWA TWP.	6 S R 10 W	C-10		,	E OF Josei F:				
. T	R R			24 DC	T 95	10:3	5 A.N	•	
in Section S T 3 . Miscellaneous S T	R R			REG		OF I	DEEDS		
Property in Section S T	R		Register of	Deeds	Sta	np &	File	Numk	er_
4. Lot No, Recorded Plat		***		ВС	D E	F G	з н	l J	к
5. Private Claims			2	6			3_		
			3			\perp			4
			4	7			 10	<u> </u>	
I, WAYNE A. MOSTROM, in a field survey onSEPTEMBER 25_, 19_95_,			- 5	<u> </u>		لــــّـــــــــــــــــــــــــــــــــ	_ <u>i_</u>	<u>l 'ï</u>	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned					,				
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current						16-1-	15	T 14-	
manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and						77		1	\top
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a				920	,—	21	—22— 	 -23 -	\top
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found					\top	+		++	十
as expressed below:			10 3	io- () -29	'-	28-	—27—	26-	十
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			11			+		1	+
			12 3	32	·—	33 	-34	35-	+
A Description of original manufacture	d someonering and/o		13	<u></u>	l	JL	Щ.	<u> </u>	L_
A. Description of original monument an		-	n;						
1865 SURVEY IN BK A, P 93	1972 SURVEY E	BY DON PIERCE	1989 SURVEY	BY M	OST	MO			
SURVEY SHOWS COR. ON & OF HWY. TO THE NW		PIPE IN MON. BOX FD. 3/4" PIPE IN MON. BOX IN C N-S RDWY & C HWY. TO NW							
CAVERS 1070 SURVEY	PK NAIL = NO	°05'28''W 97.57'	L.C.R.C. IN	<u>L</u> -4,	P-1				
SAYERS 1979 SURVEY	1037 0000		P.P. N01°W						
SHOWS "IRON IN MONUMENT BOX"	1977 SURVEY BY DOUG PIERCE U.P. N41°W 86.22'								
	FD. ½" PIPE I	IN MON. BOX	10" WALNUT			31'			
	<u> </u>		P.P. N89°E	31.69	ī				

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FD. 3/4" X 12" LONG PIPE OVER +'D STONE IN MON. BOX CORNER IS IN & HWY. TO NW, IN FENCELINE TO WEST & IN & N-S RDWY ABOVE REFERENCES FROM L.C.R.C. IN 4/167 ARE IN PLACE

> RATIFIED BY PEER GROUP IN ACCORDANCE WITH P.A. 345 ON Oct. 23, 1995 , 1995 Mus CO. REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 5/8" X 13" LONG IRON BAR IN CONC. IN MON. BOX N & W IN N. SIDE OF P.P. = EAST 31.81' N & W IN N. SIDE OF 8" WAL. = \$86°W 38.35" N & W NE SIDE OF 30" HICK. = N56°W 117.84" N & W NE SIDE OF BRACE POLE = N41°W 86.21'

COR. IS IN CL N-S RDWY & PROJ. OF CC OF M-86 TO NW & TO EAST



Signed by

14100 Surveyor's Michigan License No._

Date OCTOBER 24, 1995

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971