LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 St Joseph County Remonumentation For corners in Corner Code # St. Joseph Located In: LIBER 6 PAGE 91 (County) STATE OF MICHIGAN ST. JOSEPH COUNTY T 6S R 12W F-3 1. Public Land Survey FILED SURVEY & 1/3/2001 12:03:56 PM 2. Property Controlling Т CYNTHIA L. JARRATT in Section JAN **3 1** 2001 REGISTER OF DEEDS 3. Miscellaneous Register of Deeds Stamp & File Number Property in Sec. SECTION _ , Recorded Plat _ 5. Private Claims 3 DALE L. KESLER in a field survey on <u>JULY 5, 2000</u> hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned 5 in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a 22. 23 Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: 26 . NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. 34---- 35-Description of original monument and accessories and/or subsequent restoration: 10" Yellow Oak S 69 1/4 E 2.00 (132.0') 9" Yellow Oak N 79 deg W 2.15 (141.90') RATIFIED BY PEER GROUP Nov. 24, 1865 James Woods IN ACCORDANCE WITH P.A. 345 Stake, set fro one original bearing, now green NOV. 13 . 2000 CO. REPRESENTATIVE 1876 Norman Andrews stake from one stump of old bearings 7" W. Oak N 56 deg E 41.0" SEE PAGE TWO Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 1/2" x 12" over 1/2" bar x 36" dug 5' deep, no stone, also probed additional 1' did not reach natural soil, area has approximately 8' of fill, elevated road. Witnesses from the 1989 survey by Doug Peirce verify corner. Found 1/2" bar x 36" in monument box as described in a 1970 survey by Sayer. Accepted 1/2" x 36" iron bar as best evidence of corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set a 5/8" x 24" iron rebar with aluminum cap in a monument box in place of 1/2" x 36" iron bar and is accepted as a careful and faithful reestablishment of the position of the original corner. Nail w/tag 24" Oak tree S 40 deg 00' E 135.95" Nail w/tag 36" Oak tree S 17 deg 27' W 75.78' Nail w/tag 20" Oak tree S 36 deg 35' W 56.08' Centerline of pavement South 8.77' Surveyor's Michigan License No

A SOLING SURVEYED

REMONUMENTATION

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28-194:

REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995

A. CONTINUED

October 29, 1970 - Sayer

½" x 36" iron bar set over pointed stone with stake
30" Oak N 43 deg W 21.78 - gone
24" Walnut S 55 deg. E 71.91 - gone
22" Walnut S 17 deg E 36.56 - gone

SURVEY & BEMONIMENTATION

1976 and 1978 Peirce 3/8" iron in box

JAN 3 1 2001

1989 Peirce Found pipe in box 12" Oak S 40 deg E 121.0 C/L Road S 8.7' 6" Poplar S 51.30'

SECTION

ANTICLE TER GALLER
IN ACCOMUNACE WITH YOU SEE