

n = 10 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

For corners in	Filing Requirer	nent of Act 74, Mich	ı. P.A. 1970 Libe	r 4 PAGE 314	
ST, JOSEPH Lo FLORENCE TWP. 1. Public Land Survey	T 75 R 11W	Code#		STATE OF A ST. JOSEPA FIL	
	TR			17 MAR 97	9:32 A.M.
2. Property Controlling S_ in Section S_ 3. Miscellaneous S_ Property in Sec. S_	TRTRTRTRTR		D	CYNTHIA REGISTER	OF DEEDS
		•	R	egister of Deeds St	amp & File Number
Lot No, Recorded F Private Claims	Plat	· · · · · · · · · · · · · · · · · · ·	ı A	B C D E F G	HIJKL
		,	2 3	6 5 4	-3-1-2-1-
requirements of P.A. 74, Michigan P.A. conformance with regulations and rules to United States Department of the Interior that the corner points mentioned in lines Board of Land Surveyors or by a De recovered, found as expressed below:	of 1970, the corner points ment herefore as required in the curren Bureau of Land Management or 3, 4 and 5 above were in confor	oned in lines 1 and 2 abo t manual of survey instruct by a decree of a Court of L mance with the rules of the	that under 4 — ve were in ions of the aw and /or 6 a Michigan	7 - 8 - 9 - 11 - 16 - 17 - 16 - 19 - 19 - 19 - 19 - 19 - 19 - 19	10 11 12
NOTE: Not more than 2 corners, a on this certificate.	in the same town and range,	may be recorded	9 10 11 12	30 29 28	27 26 25 -
A. Description of original monume	nt and accessories and/or su	bsequent restoration:	13		
(G-6) 1/4 CORNER COMMON GLO 7" BURR OAK = \$29°E 10 6" BURR OAK = N61°W 3	1960 SAYERS S FOUND SQ. STO .96' 24" OAK = NW 24" OAK = NE 20" STUMP = S	URVEY NE 1.0' DEEP 57.6' 42.2' E 36.8' FENCE TO WEST	POINTED ! 34" OAK : 31" OAK :	O COMMISSION STONE IN MON. = N28°W 59.2 = N43°E 44.4 = WEST 50.90'	0 t 3 t
B. Description of corner evidence	found and/or method applied	in restoring or reestab	lishing corner:		
(G-6) FOUND 3/4"X18" IRON 44" OAK = N25°W 59. 36" OAK = WEST 50.90 CORNER FALLS 1.5' NO CORNER FALLS IN CL CORNER FALLS IN CR	.20' }' DRTH OF FENCELINE P DF ROAD TO EAST & 1	ROJ. TO WEST	F II	MAECH I	E WITH P.A. 345
C. Description of monument for co	rner and accessories establis	hed to perpetuate locat	ing the position of	the corner:	A STATE OF THE PARTY OF THE PAR
(G-6) 1/4 CORNER CONSET 5/8"X24" IRON BANEW 2.0' HIGH IN N. NEW 2.0' HIGH IN E. NEW 2.0' HIGH IN E. NEW 2.0' HIGH IN SW NEW 2.0' HIGH IN NEW 2	AR W/STD. CAP OVER: SIDE OF 36" OAK = SIDE OF 44" OAK = SIDE OF 52" OAK = SIDE OF ANCHOR POS	STONE IN MON. B WEST 50.90' N25°W 59.20' N20°W 77.72' T = S65°E 40.2	0X 7'	THE STATE OF THE S	DAVID W. MOSTROM PROFESSIONAL SURVEYOR No. 32339
Signed by J. J.W. M.	N DAVID W	<u>, mostrom</u> da	ate <u>MARCH</u>	12, 1997	PAG T
Surveyor's Michigan License No					۳۱ ت ا
		EORM APPROVI	EN RY MICHIGAN STATE	BOARD OF PROFESSIONA	