RELIGION OF THE STATE OF THE ST

SECTION

233 / 205

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1971

ال المعدد المعالمة	ION	·
For Corners in	1	LIBER 5 PAGE 225 STATE OF MICHIGAN
St. Joseph (County)	_ Located In: Comer Code #	ST. JOSEPH COUNTY
1. Public Land Survey	T_8S_R_9WD-5	FILED
	TR	22 DEC 1999 10:58:55 AM
	TR	CYNTHIA L. JARRATT
	TR	REGISTER OF DEEDS
2. Property Controlling	s	
in Section	STR	
3. Miscellaneous	sTR	
Property in Sec.	S TR	egister of Deeds Stamp & Filing Number
4. Lot No	_, Recorded Plat	. D. D. D. E. E. C. H. J. H. L. M.
5. Private Claims		ABCDEFGHIJKLM
		3
1, <u>Donald C. Andrews</u> , in a field survey on <u>November, 1999</u> , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance		
with regulations and rules therefor as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or		nited
that the corners mentioned	in lines 3, 4 and 5 above were in conformance with the rules of the Michi	igan 7 1 1 1 1 1 1
monumented, recovered, fo	r by a Decree of a Court of Law; established, re-established, monument und as expressed below:	8 - 19 20 21 22 23 24 -
NOTE: Not more than 2 corners, all in the same town and range, may be Recorded on this certificate.		9 10 30 29 28 27 26 25
		11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
A. Description of original monument and accessories and/or Subsequent restoration:		12 -31 -32 -33 -34 -35 -36 -
LCRC 4, PAGE 308		•
B. Description of corne	er evidence found and/or method applied in restoring or reestablis	hing corner:
Found Remon Capped	d Iron in Mon Box	
Geodetic Reference S having the PID of "AA	y Land Corners being located were done within specification system monument having a position order of "B" incorporate 8117" with Station Name of "IRS-F". The maximum position than 0.08 feet relative to the connecting HARN control mon	ed in the traverse network was the monument all error of each Land Comer monument being
·	nent for corner and accessories to perpetuate locating the position	n of the corner:
Found Remon Capped	d Iron in Mon Box	
It's coordinates in inter	mational feet are: Northing 104248.8973, Easting 1284714	44.8151
Witness: UP N4°W 36.80', UP S57°E 51.60', NW Cor. House FTDN. South 70.7', NE Cor. House FTDN. S20°E 73.87'		
	RATIFIED BY BEER ORG	JE OF MICHION

RATIFIED BY PEER GROUP
IN ACCORDANCE WITH P.A. 345
ON JUNE 10, 1996
INLINE CO. REPRESENTATIVE
INLINE 1996
INLINE 1

Surveyors Michigan License No. 33967

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

ANDREWS PROFESSIONAL SURVEYOR No. 33967 PROFESSIONA

REMONUMENTATION