

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42-43 N.R. 14N


Schoolcraft COUNTY

DESCRIPTION OF CORNER Section Corner common to 3-4-33-34

CORNER MONUMENT 1" X 36" Galvanized Iron Pipe

DATE MONUMENT PLACED AND WITNESSED 5-3-61 with D. St. Ours

WITNESSES TO CORNER..... 11" Hard Maple (NBT) S45°W 103½ links



17" Hard Maple (NBT) N23°E 45 links

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced 50 links south of fence corner and in intersection of roads to South, East and West.
Position checks with good corners to West.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler

REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE December 28, 1961