## **SCHOOLCRAFT COUNTY** PEER GROUP APPROVED

DATE Dec. 7, 1995

LAND CORNER RECORDATION CERTIFICATE

					• • • • •	₩.
Filing	Requirem	ent of	Act 74	Mich	DΛ	1070

JAN 3 0 1996

For	corners	in

COMMISSION

Schoolcraft  (County)  1. Public Land Survey	Located In:  T42 N R 15 W T42 N R 14 W T R	Corner Code ##  M-12  A-12	Receive Dec. Sigrid I School	. He	edbe	_19 arg	95	nt ⊋:	31	
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	T R S T R S T R S T R								Numb	er
5. Private Claims  I, Thomas P. O'Brien do hereby certify that under rein lines 1 and 2 above were i	Recorded Plat  in a field survey on  quirements of P.A. 74, Michigan P.A. or conformance with regulations and fuctions of the United States Departm	Oct.3 19 9	14 ntioned d in the	A 2 3 4 5 6 7	6 7 7 18 18 18 18 18 18 18 18 18 18 18 18 18	5 — 5 — 8 — — 17 — — 17 —	E F	G H	2-11-14-	12 13
Management or by a decree of above were in conformance wire Court of Law; established, expressed below:	a Court of Law and/or that the corner ith the rules of the Michigan Board of re-established, monumented, re-mocorners, all in the same town and	points mentioned in lines 3, Land Surveyors or by a Dec onumented, recovered, for	4 and 5 cree of a und as	8 9 10 11 12 12 12	30	29-32-	21- 28- 33-	27-	23-	25
A. Description of original	monument and accessories and/	or subsequent restoration		13		Ī	LÏ	للل		

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Sept 9, 1850 Algernon Merryweather D.S. 1/4 post. Beech 12 in. S40W 17 links Sugar 8 " N55W 40 "

M-12 Feb.25, 1976 Thomas P.O'Brien, RLS restored corner using MDOT ties to the centerline of US-2. Recorded in Liber 1 page 21 Schoolcraft County Register of Deeds.

Oct.3, 1994 Thomas P.O'Brien, PS recovered a road nail set in the centerline of Townline Road. R R spike set in 1976 had been removed during road resurfacing. Witnesses from Feb.25, 1976 survey indicate that road nail is in same position as R|R spike. Some evidence exsists from MDOT survey notes that indicate corner position may have been approximately 6.8' Easterly of monumented position. Peer review concluded that the present monumented position is acceptable, as moving East would not fit corner evidence to North. Replaced road nail with iron bar w/ 21274 cap set in monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M12 - Iron bar w/21274 cap set in monument box. Witnesses:

8" Cedar N76°W 100.46'

M-12 (East 1/4 Corner Sec. 36)

Power Pole S35°W 98.0'

Cable Riser S75°w 31.0'

Cedar Post East 40.0'

Centerline county road East 1.0'



	Ohm	8.	0	15.	_
igned by	Thomas	Р.	O'E	Brie	Ω

\_\_ Date \_\_\_\_ Dec.20, 1995

21274 Surveyor's Michigan License No. \_