MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T_43_ NR_13 = 14 W

schoolcraftCOUNT
DESCRIPTION OF CORNER Section corner bommon to Sections 7, 18, 12, and 13
DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap
WITNESSES TO CORNER 6" Cedar (S 7 NET) N 65° E 19 Links
8" Cedar (S 18 NBT) S 26° E 23 Links
10" Cedar (S_12 NBT) N_71° W_ 64 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

RESTORED. This corner was re-witnessed as set by unknown surveyor. Found squared fence post in place. Found one Tamarack B. T. bearing S 60° W 16 Links. B. T. in fair condition. Corner lies in fence line.

Corner was placed and witnessed February 26, 1958.

SURVEYORS SEAL

SIGNED Sully D. Buckler DATE 2/24/60 Billy D. Buckler