## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 43 N.R. 15 & 16 W

		Schoolcraft	COUNTY
DESCRIPTION OF CORNER	Section Corner for Secs	25-36 T43N R 16W and 30-31	T43N R15N
CORNER MONUMENT 18 x 6 1 Iron Pipe  7/15/63 by A.O. Enger, 5/13/65 checked and recorded			
DATE MONUMENT PLACED AND	7/15/63 by A.O. E withessed by Bray and Hin		recorded
FITHESSES TO CORNER	5* Y. Pine (\$30 NBT). N 37	0 E, 145 Res.	
Nº I	10 Y. Pine (\$251 NBT), N		
31	5 * Y. Pine (\$25B NBT) N	741 . 190 Iks.	
CIRCLE COMER REGISTERED	2 <sup>m</sup> Iron Pipe with Brass C	ap N 3 W, 187 Iks.	

## DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from two original BTSs found by A.O. Enger. Spruce Pine 10. S 50° E, 58 Exs. Spruce Pine 12. N 63° E, 51 Exs. C. Christonson has witness corner 2° Iron pipe with Brass Cap Marked 2530 10 rods south, which is in error 3631

as he possibly took the BT to the SE for the BT to the NEto set the Section Corner A 2<sup>m</sup> Rusted pipe is down and lies in the Lake approximately 10 rods South of his witness corner.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 6/8/1965