

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46 .. NR. 13 .. W

.. S h o o l c r a f t .. COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 2, 3, 10, and 11 ..

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap ..

WITNESSES TO CORNER 6" Balsam (S 10 NBT) S 80° W 08 Links ..

5" Soft Maple (S 11 NBT) South 42½ Links ..

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from one Hemlock Stp. bottom (possible B.T.) bearing N 29° E 14 Links.

Corner lies 1/2 chain south of woods road.

Corner was placed and witnessed July 19, 1960.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 8/11/60
REGISTERED LAND SURVEYOR
Billy D. Buckler