

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46 N. R. 16W


Schoolcraft COUNTY

DESCRIPTION OF CORNER Section corner for sections $\begin{array}{|l} 11 \\ 14 \end{array} | \begin{array}{|l} 12 \\ 13 \end{array}$

CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap.

DATE MONUMENT PLACED AND WITNESSED 9-12-61

WITNESSES TO CORNER..... 10" cedar (S 13 NBT) S 85°E 35½ links



6" Tamarack (S14 NBT) S64°W 40½ links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from Tamarack to NW with old faces. No iron marks visible. Several blazes in vicinity.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE January 2, 1962
REGISTERED LAND SURVEYOR
Billy D. Buckler