MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD



T. 42 NR ... W

				_S_cheeleraftCOUNI
DESCRIPTION	OF	CORNER	1/4_cormer	between Sections 34 and 35
DESCRIPTION	OF	CORNER	MONUMENT	1" Pipe with 4" Brass Cap
WITNESSES	то	CORNER	15" Red_Pine	(1/4s NBI) S_87° E 104_1/2 Links
			8" Red Pine	(1/4s_NBT) N 39° E30 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

RESTORED. This corner was re-established midway and on line between two Section

Corners. Found old blazes about 1.00 chains to east. No evidence at Corner.

Corner was placed and witnessed June 8, 1960 with Frank J. Bray.

SURVEYORS SEAL

SIGNED SULLAND SURVEYOR

Billy D. Buckler

Billy D. Buckler