LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in School craft		•	1							
(County)	Located in:	Corner Code #								
1. Public Land Survey	T <u>47#</u> R T R T R									
Property Controlling in Section Miscellaneous Property in Sec.	S TR S TR S TR S TR		R	egiste	r of De	eds St	amp l	l File I	Numb	-81
4. Lot No, Reco	orded Plat		1 Å	ВС	D E	F	5 <u>H</u>	1 3	ĸ	L
		-	2	<u> </u>	- <u> </u>		 	- - !		1.
Chashas V Savashashi		May 13 1997	3 —	╅	╅	+		╁┼		╀
requirements of P.A. 74 Michig	,, in a field survey on	, 19 do hereby state that wer points mentioned in lines 1 and 2 above w	under 4	·∤—	- წ—	_ કે	10-	11	ı——-	12
conformance with regulations an United States Department of the that the corner points mentioned	d rules therefore as requin Interior, Bureau of Land N d in lines 3, 4 and 5 above y a Decree of a Court o	ed in the current manual of survey instructions fanagement or by a decree of a Court of Law a were in conformance with the rules of the Mic of Law; established, re-established, monum	of the one of the order	18	17-	-16	-15-	14	<u> </u>	13
NOTE: Not more than 2 and			و	ï					\	1
on this certificate.	ners, as in the same tow	n and range, may be recorded	10-	30_	-29 	-28	27_	26	;—2	 S-
			11	31	32	-33-	34	35		 36-
A. Description of original mo	onument and accessor	ies and/or subsequent restoration:	13							_

A. Description of original monument and accessories and/or subsequent restoration:
(C10) Quarter corner common to Sections 29-30. Original corner location perpetuated in 1953 by Dean C. DetaMater from an original B.T. in good condition. Description of corner monument: I" pipe with 4" brass cap. Witnesses: 24" M. Pine stump S53E 120 links, 16" R. Pine M64M 153 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C10) Recovered the 1953 monument as described, a 1° ID iron pipe capped with a 4° dia. brass MI Dept. of Conservation tablet, in good condition, and at record bearing and distance from the 1953 M. Pine stump witness, found with notch and scribing still visible. The R. Pine witness has been destroyed. The original Y. Pine BT N24E, 23 links, now a stump with no markings visible, was also recovered at record bearing and distance. Left the monument in place and marked four new accessories as described below. Corner recovered and rewitnessed by T. Stark and D.Lampela, Newberry District Office. Corner is about 45' south of a trail road.

C. Description of monumen (C10) Found 1" pipe with 4"	for corner and accessories established	to perpetuate locating the position of the stationary
Slazed, scribed, and set mea	· · · · · · · · · · · · · · · · · · ·	
	initing werra	
in the following:		* STEPHAN J. *
10" Red Pine South 19.75'	"1/4S MBT"	* SZYSZKOSKI
7" Twin W. Pine S44W 44.65"	*1/4S NBT*	LAND
8" Jack Pine N72N 46.25"	"1/4S MBT"	SURVEYOR
5" Red Pine M02E 24.60'	"1/4S NBT"	301 /. /
Placed a 5° squared and scri	ped post	33986 No.
adjacent. Bearings are magne	ic.	THE LUCK
_		

Signed by Stephan J. slags. Book. Date 3/25/98

Surveyor's Michigan License No. 33986