CONS. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N.R. 16W

	Schoolcraft	COUNTY
DESCRIPTION OF CORNER _ Sec. Cor. for Secs. 9, 10	, 15 and 16.	
CORNER MONUMENT 1" Iron pipe with 4" Aluminum	Cap.	
DATE MONUMENT PLACED AND WITHESSED 5-15-63		
WITHESSES TO CORNER 20" W. Pine (S. 10) (N.B.T.), N. 59 ⁰ E., 119 Iks.	
3" W. Pine (X)	, s. 40 ⁰ W., 63 Lks.	
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced at wood post. Found 12" Tamarack (N. 75° E. 117 Iks.) down and rotted; inverted notch in over growth and scar tissue found of faces.

SURVEYOR'S SEAL

SIGNED Silly D. Buckler DATE 1/2/64