CONS. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

	T47 N. R1	<u>6w</u>		
		Schoolcraft		COUNTY
DESCRIPTION OF CORNER	1 Corner for Sections 8/9			
CORNER MONUMENT	1" Iron Pipe with 4" Brass C	ap		
DATE MONUMENT PLACED AND	9-21-61			
WITHESSES TO CORNER	5" Black Spruce (NBT &S) S67 ⁰ W	15 links	
N	4" black Spruce (NBT4S) \$35°E	17½ links	
\$9				
+	AMD			
CIRCLE CORNER REGISTERED	· 			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from Tamarack 6" N50°W 04 links original B.T. with notch and iron marks visible, rotted and in poor condition.

SURVEYOR'S SEAL

18NED Silly C. Luckler DATE December

REGISTERED LAND SURVEYOR

PARTIE D. Problem