MAY 28 1997

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Shiawassee (County)	SSION Located in:	Corner Code #	RECORDED
1. Public Land Survey	T <u>5N</u> R <u>2E</u> T R	<u>K-9</u>	96 NOV 18 PM 3: 39 REGISTER OF DEEDS
Property Controlling     in Section	TR TR STR S T R		Staye Sheedle SHIAWASSEE COUNTY. MICH.
3. Miscellaneous Property in Sec.	S T R S T R		ABCDEFGHIJK
4. Lot No 5. Private Claims	, Recorded Plat		2 5 4 3 2
			3

I, Mark L. VanRaemdonck, in a field survey on November 6, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the current points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range. may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- 1.) Original: Joseph Wampler, D.S., 1826.

Monument: Wood post

Accessories:

Beech 16 S82°W 10 1/2

Sugar 5 N49°E 12 1/2

2.) Elmer F. Joslin, County Surveyor, April, 1902.

Monument: Found 1 1/4" gas pipe
Accessories: Elm 9" N30 1/2°E 54 1/4 links

W. Oak 6" S22 3/4°E 90 1/2 links

(Book F, page 20)

3.) John F. Quine, L.C.R.C. recorded Liber 1, page 571, 4/7/75.

Monument: Found 1 1/4" gas pipe 6" deep. Brought to surface with 3/8" x 6" iron rod
Accessories: Road name sign post NW 43.6'
Tele. cable warning sign at NE corner of tele. pole SW ? (1902 BT) Oak 30" S22 3/4°E 59.6' (90 1/2 links + 1/2 of 6" diameter = 59.98')

Stop sign post NE 46.2'

7/18/1964 Field Book 7, page 48

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1 1/2" gas pipe as referenced in no. 2 and no. 3 above. Accepted this location as the original corner position based on the best available evidence. Excavation for Harrison Marker provided no further evidence. The gas pipe had been forged to a point on the bottom. Found no conflicting evidence.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner:

Removed gas pipe and installed a standard Shiawassee County Harrison Marker monument. The monument was stamped "REMON 24622" and is witnessed by the following accessories: L OF MICHIGA

N45°E 86.27' Set N&T in S. face util. pole N60°W 43.79' E. face road sign post at base S40°W 41.13' Top cen. tele. cable box \$20°W 40.00' Set rerod & cap in shoulder

Much L. Van Ren Lal

24522 CRED BAND

6

7

8

10

11

12

13

Surveyor's Michigan License No. 24622

PROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS JAN 18, 1971] REVISED MAY 14, 1975 REVISED JAN., 1983

MARK L

**VANRAEMDONC** SURVEYOR No.

County Remonumentation Peer Review Group