DEC 1 5 1993

COMMISSION

for corners in

M-11

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 REMONUMENTATION

RECORDED

93 DEC -6 AM IO: 50	93	DEC	-5	M	10:	56
---------------------	----	-----	----	---	-----	----

Sh	Tawassee (County)		Located In:	Corner Code ##
	Public Land Survey	**	7 5N R 2E	M-11
	·		Υ R Υ R	
			T R	
	Property Controlling	S _	T R	
	in Section	S_	T R	
	Miscellaneous	S _	T R	
	Property in Sec.	\$	TR	

REGISTER OF THEELE Thyen Therein SHIZZASSEE COUNTY, MICH


Register of Deeds Stamp & File Number

___ , Recorded Plat . Private Claims

Norman C. Caldwell , in a field survey on November o hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned n lines 1 and 2 above were in conformance with regulations and rules therefore as required in the urrent manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a court of Law: established, re-established, monumented, re-monumented, recovered, found as xpressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:



Sec. cor., 25 & 36, T5N-R2E & Sec. 30 & 31, T5N-R3E

Wood post placed by J. Wampler, 1826 \$31°W 6 lks. (3.96°) 5" Birch N21°W 21 lks. (13.86°) 6" Birch

Survey by E. F. Joslin, Co. Surveyor, Feb. 1900, recorded in Book E, pgs. 246 & 247, S.C.R. 1" iron pipe at corner \$53 1/4°E 59.5 lks. (39.27') 6" Maple \$21 3/4°E 95.75 lks. (63.20') 12" B. Walnut

Unrecorded survey by R. L. Mitchell, 1976 N45°E 41.15' N & F in Tele. pole s45°E 39.15' N & F in 20" Maple

L.C.R.C. by E. S. Brewer, August 1978 recorded in Corners L. 2, pg. 196 Find. 1 1/4" pipe set by others in 1976 N45°E 41.15' Nail in Iele. pole S45°E 39.1' Nail in 24" Maple Nail in 24" Maple

Unrecorded survey by A. F. Miller, 1979 Fnd. 1 1/4" pipe N45°W 36.05' Road sign N45°E 41.15' Tele. Pole S45°E 39.15' N & F 20" Maple

Survey by M. L. Vanraemdonck, 1984 recorded in Surveys L. 4, pg. 172 fnd. 1 1/4" pipe N45°W 35.90' Road sign N45°E 41.15' Tele. Pole \$45°E 39.10' 24" Maple South 4' CL Braden CL Braden Road

. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

-11 Sec. cor., 25 & 36, T5N-R2E & Sec. 30 & 31, T5N-R3E

Fnd. 1 1/4" pipe per Co. Surveyor's records, L. 2, pg. 196 of Corners, L. 4, pg. 172 of Surveys and other records. Replaced with standard 20" Harrison marker as approved by Shiawassee County Peer Review Group and is accepted as the best available evidence of the position of the original corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

-11 Sec. cor., 25 & 36, T5N-R2E & Sec. 30 & 31, T5N-R3E

Fnd. 1 1/4" pipe per Co. Surveyor's records, L. 2, pg. 196 of Corners, L. 4, pg. 172 of Surveys and other records. Replaced with standard 20" Harrison marker as approved by Shiawassee County Peer Review Group and is accepted as the best available evidence of the position of the original corner. S45°E 39.67' Set N & T #12018 NE fc 24" Maple (R-tree) N45°E 41.10' Fnd p.k. in Tele. Pole N10°W 71.78' Chis. "+" top center W. end 18" CMP culvert N20°E 73.45' Chis. "+" top center E. end 18" CMP culvert

∎rveyor's Michigan License No. _____

OF BICHIO OF MICHIGA NORMAN C. CALCY/ELL POPESSIONAL ROYEVUE 1au DESSION DESSION

ZO NOV

gned by 12018

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983

Date