MAY 28 1897

REMONUMENTATION

RECORDED

LAND CORNER RECORDATION CERTIFICATE

96 AUG 16 PM 2: 37

32

COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

REGISTER OF DEEDS

For corners in								E.			
Shiawassee		Located In:		Corner Code #	ĺ		Back	Such	4		
(County)				•	E.	CHIAW	<i>) 6</i> NGSER	COUNT	LA WI	CH	
•						V1 0259	<i>P</i> ^ ∪ CCLL	. DOUNT	11.719	UII.	
1. Public Land Survey		T 51	N R 3E	<u>M-9</u>							
•			R								
2 Property Controlling	S	1 T	R								
2. Property Controlling in Section	s	— <u>`</u> ;——	Ř								
3. Miscellaneous	s	_	R		Rea	ister of D	eeds S	tamp &	File	Numbe	er
Property in Sec.	s -	_ _	R								
4. Lot No, Recorded Plat 5. Private Claims						1 A B G	C D	E F G	Н	JK	L M
						2 6	- 5	4	-3-	2-	1-1-
						3					<u> </u>
I, Norman C. Cal				April 1996, A. of 1970, the corner points mention	ned	4 - 7	- 8	9	10	11-	12
				ind rules therefore as required in		5	· ·				,
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5						6 18	17	16	15	14	13
				ner points mentioned in lines 3, 4 and Lof Land Surveyors or by a Decree of		7					
Court of Law; established, re-established, monumented, re-monumented, recovered, found as						8 19	20	21	22	- 23	24
expressed below:						9		 			
NOTE: Not more than 4 corners, all in the same town and range, may be recorded					d	10 30	29	28	- 27 -	26	25
on this cortifie		,				11		┃ ┈┈┈┤╌		لسيسا	

- Description of original monument and accessories and/or subsequent restoration:
- M-9 Cor. common to 24 & 25, T5N-R3E & 19 & 30, T5N-R4E

Wood post placed by J. Mullett, 1823. N 41 E 2.00 lks (132.00') 7" Tamarack, S 1 W 99 lks (65.34') 6" Tamarack.

Survey by L. Mason, 1879, recorded in Shiawassee County Surveyor Records 1874- 1883, P. 236 and 1879- 1900 P. 34. Monument not given, N 54 1/2 E 67 1/4 lks (44.38) 8" Tamarack

Survey by P.L. Benton, 1972, unrecorded survey Job No. 72-5106, Monument not given. N 35 E 64.59' 12" Poplar, N 20 W 49.78', 15" Oak, N 70 W 112.52' Spike 10" W. Oak, South 32.50' Centerline fence post, Fence line to S. 1.0' +/- West.

L.C.R.C. by M.D. Pike, 1974, recorded in L. 1 P. 198 of corners. Found 1/2* iron, North 94.20' 14" Oak, N 15 W 50.00' 12" Oak, South 32.35' Fence post.

Survey by E.J. McCombs, 1974. Consumers Power Company drawing S-F 17694. Monument and reference not

- Description of corner evidence found and/or method applied in restoring or reestablishing corner: R
- M-9 Sec. Cor. common to 24 & 25, T5N-R3E and 19 & 30, T5N-R4E

Found record 1/2" bar by Benton.

This is a common corner with Sections 19 & 30, T5N-R4E. Reviewed and accepted by the Shiawassee County Peer Review Group on 19 March 1996 and accepted as the best available evidence of the position of the original corner.

- Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- Sec. Cor. common to 24 & 25, T5N-R3E and 19 & 30, T5N-R4E

Found record 1/2" bar. Replaced with a standard Harrison Monument in a monument box in the physical centerline of Beard Road.

References:

N 20 W 47.20' N 30 B 37.40' #12018 tag in 5" Elm Center top of 24° CMP Center top of 24° CMP S 70 E 37.48

#12018 tag in RR tie fence corner post

Remonumentation Peer Review Group

Burveyor's Michigan License No.

Signed by

D SURVEYORS, JAN. 28, 1971

OF WICH AND

NORMAN C.

CALDWELL

PROFESSIONAL SURVEYOR No. 12018

POFESSIO