MAY - 1 1995

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

For corners	INCOMMENCE	

Shiawassee			Locat	ed in:	Corner Code #	
	(County)					
1	Public Land Survey		T_71	N R 1E	(K-11)	
١.	rupho Lana Carrey		T	R		
			Т —	R		
			Τ	R		
2.	Property Controlling	S	т	R		
	in Section	s	T	R		
3.	Miscellaneous	s	T	R		
	Property in Sec.	s	т	R		
4.	Lot No	, Re	corded Pl	at		

94 NOV 16 PM 3: 43 REGISTER OF DEEDS

Register of Deeds Stamp & File Number

	A E	3 (	; D	E F	9 H	iJ	K L N
2	_ {		5_	14-	3	  2	
3			$\Box$	$\perp \perp$			4
4			    	ļģ-	—10 <u> —</u>	<del>1</del> 1	L12-
5	Щ			++	$\bot$	++	<del>                                     </del>
6	<b>—</b> 1	3—	_1 <u>7</u> -	16-	<u> </u>	14-	<u> </u>
7	Ш			$\perp \perp$	<del>      -</del>		
8	1	9	20-	<u> </u>	<u></u>	<u>2</u> 3	24
9	_		$\perp$	-	+	<del>                                     </del>	<del>                                     </del>
10	—з	)	29-	28	27	<u> </u>	<u>25</u>
11				+ $+$		+	<b>-</b>
12	<u></u> _з		-32-	<b>—</b> з¦,_	34	<b>—з</b> 5—	36
13	Ш						

I, Mark L. VanRaemdonck, in a filed survey on October 21, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the current points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, remonumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- 1.) Original: Robinson Thomas, D.S. 1831.

Monument: Wood post

5. Private Claims

Accessories: B. Oak 8 N63°E 37 links 4 N88°W 85 links do

2.) E. L. Mason, Deputy County Surveyor. 3/7 1858

Monument: Not given

Accessories: B. Oak 12 S56°W 601/4 B. Oak 12 S54°W 1/8

3.) R. Kraft: Unrecorded survey Section 25. 05/22/72

Monument: "T" iron

Accessories: Property corner 47.10' Northeast County road sign 45.8' Southeast

County road sign 31.5' Northwest

APPROVED

County Remonumentation Peer Review Group

10/18/94 M.L.V.

4.) M. VanRaemdonck: Survey recorded Liber 4, page 109, 12/19/83.

Monument: Found "T" iron

Accessories: N45°W 30.25' Southeast face road sign post

38.0' Southwest face cable marker post Northwest corner yield sign post S30°F 45.0' Northeast face 4" Blue Spruce S85°W 73.55'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original monument and accessories have been obliterated. Accessories by E. L. Mason (03/07/1858) have been obliterated. Found "T" iron as referenced in no.'s 3 and 4 above. This location fits well with measurements along West line and with G.L.O. distance and County Surveyor's distances to M-11. Accepted this location as the best available evidence of the original corner location. Excavation for installation of Harrison and installant was a supervised by the supervise marker provided no further evidence.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner:

Set standard Harrison marker stamped "REMON 24622" and witnessed by the following accessorles:

37.28' Top center telephone cable box N30°W 98.91' Set N&T in East face 12" Elm N10°W 100.53' Set N&T in West face 12" Elm

64.28' Center East face flag pole

Surveyor's Michigan License No. 24622

PED LAND Date Nov. 9, 199

MARK L VANRAEMDONCK

LAND

SURVEYOR

No. 24622

IR PG

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS JAN 18, 1971) REVISED MAY 14, 1975 REVISED JAN., 1983