

NOV 1 0 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

97 OCT 15 PM 12: 15

REGISTER	OF DEEDS
	N.

Tayer ;	Sulla
SHIAVIASSIE	COUNTY, MICH.

For corners in								£.		
Shiawassee		Located In: Corner Code #				اون مردمیده	ayer	Phase	tas.	
(County)		Middlebury Townsh	ip		-	SHLAVI	ASSIE	сопи,	14. MIC	CH.
1. Public Land Sur	rvey	T 7N R 1E T R T R	L-9							
Property Control in Section Miscellaneous	s	T R T R		Registe	r of D	eeds S	Stamp	& File	Numb	er
Property in Sec	. s	TR			•					
4. Lot No.	, Recorde	d Plat		1 A	\ В	C ·D	E F	э н	ı J K	L M
o. Trivuto olamio				2	6	- 5 -	- 4	3	2	- 1
I, Wendy A. P	apineau	, in a field survey o	on June 19 97 of 1970, the corner points mentioned		7	8	9.	10	11	12
in lines 1 and 2 above current manual of sur	e were in confo vey instructions	ormance with regulations and of the United States Departr	d rules therefore as required in the ment of the Interior, Bureau of Land	6	18	17	16	15	14	13
above were in conform	nance with the r	ules of the Michigan Board o	r points mentioned in lines 3, 4 and 5 f Land Surveyors or by a Decree of a nonumented, recovered, found as	. 8 . 9	19	20	21	22	23	24
•	than 4 corners	s, all in the same town a	nd range, may be recorded	10	30	29	28	27	26	25
on this ce				11 12	31	32	33	34	35	36
A. Description o	f original mon	nument and accessories a	and/or subsequent restoration:	13 L		<u></u>	<u> </u>	L		L
L-9 1/4 Corne	er Section 24	4 & 25, T7N-R1E								
		R. Thomas, D.S., Jan. 6.93') 4" Elm	1831							

N 27 W 23 lks (15.18') 5" Ash

Survey by I.E. Brands, Surveyor, 1912, recorded in sm. red misc. drain book Monument and references not given

Surveys by M.L. Vanraemdonck, 1995 & 1996 Recorded L. 7 P. 259 and P. 669, S.C.R. Fnd SQ. Bolt

Find SQ. Bolt South 33.00' R & C #24622 North 24.54' Bolt & Tag S.C.S. BM S. Fc Wd Anchor post N 65 E 77.38' Set N & T W. Fc SW Trunk of 4-12" Poplar S 70 E 59.15' Set N & T N. Fc 6" Elm

APPROVED

County Remonumentation

Description of corner evidence found and/or method applied in restoring or reestablishing corner evidence Feview Group

1/4 Corner Section 24 & 25, T7N-R1E L-9

Find 1/2" solid rod with 1" square head per records. This position fits well with I.E. Brands record (C.S. 80.32ch= 5301.12' Meas.= 5309.67') and very closely to a split (West= 2655.36' East= 2654.31'). This position falls 1.43' South of a straight line between section corners.

This position is accepted as the best available evidence of the position of the original corner.

Approved by the Shiawassee County Peer Review Group, Sept. 4, 1997

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-9 1/4 Corner Section 24 & 25, T7N-R1E

> Replaced 1/2" solid rod with 1" square head with a standard 20" Harrison monument in centerline gravel road, 6" below surface.

South 33.00'

24.53' North

1/2" rod with cap #24622
Bolt and S.C.S. BM tag in South face wood anchor post
Set new nail and tag #39096 in West face on SW trunk of 4-12" Poplar
Set new nail and tag #39096 in North face of twin 6" Elm

S70E

OF MICH WENDY A. PAPINEAU **PROFESSIONAL** SURVEYOR No. 41919 POFESSIO

Surveyor's Michigan License No.

STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971