## SURVEY & REMONUMENTATION

MAY - 1 1995 LAND CORNER RECORDATION CERTIFICATE

RECORDED

	Filing Requ	direment of Act 74, which. P.	.A. 1970
For corners in	DMMISSION		94 NOV 16 PM 3: 44
Shlawassee (County)	Located in:	Corner Code #	REGISTER OF DEEDS
1. Public Land Survey	T <u>7N</u> R <u>1E</u> TR TR 		Shinwasser County. MICH.
2. Property Controlling	STR		
in Section	\$TR		
3. Miscellaneous Property in Sec.	STR S T R		Register of Deeds Stamp & File Number
Property in Oco.	·		A B C D E F G H I J K L
4. Lot No	, Recorded Plat		
5. Private Claims			2 - 6 5 - + - 4 3 - + - 2 - + - 1
			3 4 7 8 9 10 11 12 -
I, Mark L. VanRaemdonck, In a filed survey on October 21, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the current points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, remonumented, recovered, found as expressed below:			5 18 17 16 15 14 13 13 13 15 16 17 18 18 18 18 18 18 18 18 18 18 18 18 18
			9 40 20 24 22 23 24
			10 -30 -29 -28 -27 -26 -25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			11 12 31 32 33 34 35 36- 13
A. Description of original	I monument and accessories and	or subsequent restoration:	
Original: Robert Clark Jr			

APPROVED

County Remonumentation Peer Review Group 10/18/94 M.L.V.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original monument and accessories have been obliterated. Re-established the location of the South ½ corner of Section 36, T7N-R1E using the single proportion method. This location is at the centerline of the asphalt surface of Hibbard Road, and in line with an old fence line running North. This location is accepted as the careful and faithful re-establishment of the original corner location. Excavation for Harrison marker installation provided no further evidence.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner:

Set standard Harrison marker stamped "REMON 24622" and witnessed by the following accessories:

N25°W 36.63' Set N&T Southwest face 24" Maple S25°W 39.47' Set N&T East face 24" Maple N60°E 62.36' Set N&T South face 18" Hickory S70°E 62.00' Top center West end 12" concrete culv.

Accessories: Maple 8 N671/2°E 12 links

10 N80°W 26 links

do

OF MICHIER MARK L VANRAEMDONCH LAND SURVEYOR No. 24622

Surveyor's Michigan License No. 24622

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS. JAN 18, 1971) REVISED MAY 14, 1975 REVISED JAN., 1983