SURVEY & **REMONUMENTATION**

MAY - 1 190E

I AND CORNER RECORDATION CERTIFICATE h. P.A. 1970

RECORDED

1185 7 5		irement of Act 74, Mic	
For corners in CO	MMISSION		
	Located	d in:	Corner Code #
(County)			
Public Land Survey	T <u>7N</u>	R <u>1E</u>	(M-11)
•	Т	R	
	<u>T</u>	R	· · · · · · · · · · · · · · · · · · ·
	Τ	R	
2. Property Controlling	sT	R	<u></u>
in Section	\$T	R	
3. Miscellaneous	ST	R	
Property in Sec.	\$T	R	***
4. Lot No.	, Recorded Plat		

94 NOV 16 PM 3: 44 REGISTER OF DEEDS Laye Shulla

Register of Deeds Stamp & File Number

į	A E	3 (: [) E	-	- (G I	<u>H 1</u>)	(L M
2	<u> </u>						_,	}	Ĺ,	<u> </u>	1	
	Γ,			,			,	ĺ	•	Ī		ìΙ
3									Г.	Ţ		П
4	7		<u>—</u> წ		۹ – ا	}—	-1	0— 1	_1	1—- 	1	ľΤ
5		<u> </u>					_			-	-	H
6	_1	8	1	7	_1	6	1	5—	<u> </u>	4	-1	3-
7								_		_		
8	_1	9	2)	_2	1	2	2—	_2	3	2	4—
9												
10	-3	n_			2	R	_2] 7	2	 R	 -2	5
		Ĭ					_			Ĭ		
11							_					
12	<u> </u>	1-	—3 <u>;</u>	2	-3	3—	3	4	—3	5—	<u>-3</u>	D
13	نـــا	لــــا			j					L	ļ.,l	

I, Mark L. VanRaemdonck, in a filed survey on October 21, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the current points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, remonumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- 1.) Original: Robert Clark Jr. 1831 Monument: Wood post

5. Private Claims

Accessories: Beech 10 N131/2°E 10 links S19°W do 9 links

2.) M. VanRaemdonck: Unrecorded survey for Shiawassee County Road Commission 09/26/89

Monument: Set rerod & cap #24622 in centerline Baldwin Road at 69 links (G.L.O. jog) South of Northwest corner Section 31, T7N-R2E.

Accessories: North 45.54' Iron pin at Northwest corner Section 31, T7N-R2E

N20°W 84.84' Set N&T in East face 24" Maple N45°W 82.48' Fnd. N&washer East face utl. pole N15°E 79.65' SW face road sign post

N25°W 102.20' SE corner brick porch foundation

APPROVED

County Remonumentation Peer Review Group 10/18/94 MLV.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original monument and accessories have been obliterated. Located corner A-11 of T7N-R2E (Northwest corner Section 31) as per L.C.R.C. Liber 1, page 251. (This corner has a good history.) Found rerod and cap #24622 in center of Baldwin Road 45.54 feet (69 links) South of corner. I reestablished this corner location by projecting the line between A-11, T7N-R2E and M-10, T7N-R1E South 45.54 feet from A-11, T7N-R2E, as directed by the Peer Review Group. This location is 0.80 feet West of the found rerod & cap. Excavation for Harrison Marker provided no further evidence. This location is accepted as the careful and faithful re-establishment of the position of the original corner location.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner:

Set standard Harrison Marker, stamped "REMON 24622" and witnessed by the following accessories:

North 45.54' Iron pin at Northwest corner Section 31, T7N-R2E N45°W 81.67' Set N&T in South face utl. pole S65°W 29.71' Set rerod & cap #24622 S50°E 16.17' Set rerod & cap #24622

OF MICHIGAN MARK L. VANRAEMDONCK LAND SURVEYOR P.D. LAND

ORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS JAN 18, 1971; REVISED MAY 14, 1975 REVISED JAN., 1983

LIBER IR PG 90

Surveyor's Michigan License No. 24622