MAY - 1 1995

LAND CORNER RECORDATION CERTIFICATE

RECORDED

territoria de la compansión de la compan

Ear	cornere	in	

5. Private Claims_


COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970

94 NOV 16 PM 3: 44

REGISTER OF DEEDS

Corner Code # Located in: Shiawassee 5 4 1 (County) 1. Public Land Survey 2. Property Controlling in Section 3 Miscellaneous Property in Sec. _, Recorded Plat_ 4. Lot No.

Register of Deeds Stamp & File Number



I, Mark L. VanRaemdonck, in a filed survey on October 21, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the current points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, remonumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- 1.) Original: Joseph Wampler, D.S. 1823.

Monument: Wood post Accessories: Elm 16 N3°E 19

Lynn 8 S18°W 5

2.) Ezra L. Mason, County Surveyor. No date.

Monument: Not given

Accessories: Elm 40 S50°E 88

APPROVED

County Remonumentation Peer Review Group 10/18/94 M.L.V.

3.) M. VanRaemdonck: L.C.R.C. Liber 1, page 437. 07/05/85
Set the Southwest corner of Section 31, T7N-R2E, at the G.L.O. distance 16.10 chains West of the Northwest corner of Section 6, T6N-R2E.

Monument: Rerod and cap #24622

Accessories: S30°E 62.65' North face Power Pole
N70°E 56.68' Top center North end 12" CMP culv.
N20°E 50.75' Top center South end 12" concrete culv. 4.50' Physical centerline Hibbard Road South N30°W 40,90' Southeast face road sign post

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original monument and accessories have been obliterated. Accessories from E. L. Mason have been obliterated. Found rerod with unreadable Verified this to be the same location as referred to in L.C.R.C. Liber 2, page 437 and is accepted as the best available evidence of the position of the original corner location. Excavation for Harrison marker provided no further evidence.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner:

Replaced rerod with standard Harrison marker stamped "REMON 24622" and witnessed by the following accessories

South

21.24' East edge East leg double arrow sign 62.74' Set N&T West face utl. pole 68.36' Set N&T South face 18" Hickory

N65°W 79.00' Set N&T South face 30" Maple

k L. Vinfender

Surveyor's Michigan License No. 24622

E TATO

MARK L.

VANRAEMDONCK

LAND SURVEYOR No.

OF MICHIGA

Huitelle

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORG JAN 18, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

LIBER IR