## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For	corners in			
_	Shiawassee (County)	Located in:	Corner Code #	SURVEY & REMONUMENTATION
1.	Public Land Survey	T_8N_R_1E_ TR		NOV 0 3 1998
2.	Property Controlling	TR TR STR		SECTION
3.	In Section Miscellaneous Property in Secot No	STR STR STR, Recorded Plat		Register of Deeds Stamp & File Number
5. F	Private Claims	, Necolded Flat		The state of the s
und line requ of that that the esta	er requirements of P.A. s 1 and 2 above were in uired in the current man he Interior, Bureau of La the corner points ment rules of the Michigan B	in a field survey on June 16, 19, 74, Michigan P.A. of 1970, the conformance with regulations and of survey instructions of the and Management or by a decreationed in lines 3, 4 and 5 above card of Land Surveyors or by a , monumented, re-monumented	corner points mentioned in and rules therefore as United States Department of a Court of Law and/or were in conformance with Decree of a Court of Law;	2 -6 - 5 - 4 - 3 - 2 - 1 - 3 - 4 - 7 - 8 - 9 - 10 - 11 - 12 - 5 - 14 - 13 - 7 - 8 - 19 - 20 - 21 - 22 - 23 - 24 - 9
	TE: Not more than a orded on this certifi	? corners, all in the same to cate.	own and range, may be	10 32 23 23 27 28 25 11 12 21 22 23 24 25 25 25
A. I	Description of original r	nonument and accessories and	or subsequent restoration:	10
1.	Original, R. Thomas, Monument: Wood po Accessories: Lynn 3 i Elm 24	st	***	ROVED emonumentation
2.	Monument: Found dra Accessories: Concret	cords Field Book, CR-21, page 73, A ng tooth, left it and put in broken tile e anchor post N1°E 24' N36 3/4°W 34-6"	Door D	oview Group
3.	John Quine, LCRC, re Monument: Found dra Accessories: Wooder Concret	acorded Liber 1, page 506, March 14, ag tooth, 12" deep, brought up with 3/4 comer fence post S 22.25" a corner fence post N 24.1' N80°E 112.8'	1975 4"X6" pipe set over drag tooth.	MARK L.  * VANRAEMONCK *  PROFESSIONAL SURVEYOR  No.  24822  shing corner:
4.	Monument: Found 3/4	Survey recorded Liber 6, page 885, J P pipe 4" deep o LCRC recorded Liber 1, page 506.	uly 8, 1994	PROFESSIONAL SURVEYOR No. 24622 shing corner:
B. [	Description of corner ev	idence found and/or method ap	plied in restoring or re-establi	shing corner:
	Found bent 3/4" pipe of drag tooth. Found p	over drag tooth, found pleces of brick. Jointed stone lying down on East side fit. I accepted the location of the drag	Also found 5/8" pin 0.4" East and of drag tooth. I disregarded the 5/8	U.3' NOTUS I" pin since
C. I	Description of monumer	nt for corner and accessories to	perpetuate locating the positi	ion of the corner:
	replaced the drag tooth with a Standard Shiawassee County Harrison Marker Monument, stamped "Remon P.S. 24622" and witnessed by the following accessories:			
	North 23,48' 1 N20"E 20,10' 1 N65"E 42,18' 1	Set Nail & Tag 24622 in W., face 16" A fop cen. conc. post (leens South) fop cen. W., end 18" CMP culv. fop cen. E., end 18" CMP culv. Cen. S., face 48" Oak 97 Corner M-9	ash	

Lb-1 Pe-259

Surveyor's Michigan License No.

3007706 Page: 1 of 1 10/27/1998 03:22P

JAN 18, 1971 REVISED MAY 14, 1976 REVISED JAN., 1983

Date <u>SEPT. 10, 1998</u>